

8 Downside
Crescent

New hedge behind low
level wall

New timber clad bin store

Reception

Reception

Hall

Utility

WC

Boot
Room

6 Downside
Crescent

4 Downside
Crescent

Driveway
resurfaced with dark grey
setts in herringbone
pattern

New hedge behind low
level wall with metal railing

New brick pier to match
existing between no.6 & 4

Opening width as existing

Crossover as existing

5m
4m
3m
2m
1m
0m

