



Key:

- Approximate line of existing masonry crack
- Proposed 6mm Helifix Helibar repair
- Proposed masonry repair

Notes:

Helibar repair (refer to manufacturers installation guidelines)

- Provide 6mm Helibar with HeliBond grout
- Depth of slot in to the masonry to be 35mm to 40mm
- Height of slot to be equal to full mortar joint height, with minimum of 8mm
- Helibar to extend min. 500mm beyond the crack either side
- Helibars to be installed at max. 450mm (6 courses) vertical spacing

