KEY:

1. DINING ROOM

Lift and re-lay floor and floor joists on DPM – subject to survey.

Remove damp affected plaster and replaster. Include to renew wainscotting in conjunction.

Gioucester



Lift and discard non-original floorboards. Lift and re-lay joists on damp proof membrane. Reduce height of subfloor piers to achieve continuous floor finish between kitchen and dining room.

Remove damp affected plaster and replaster incorporating chemical damp proof course to flank wall.


3. CONSERVATORY

Remove concrete floor and re-lay to include duct to reintroduce cross-flow ventilation to subfloor.

Remove damp affected plaster and replaster.

4. REAR ROOM

Remove damp affected plaster and replaster.



Im Basement level


38 Gloucester Crescent, LONDON, MUI TOL


Jamestown

KEY:

1. VAULT

Remove failed cementitious tanking to vault and lobby. Replace tanking with drained cavity system to comply with BS8102 2009. Cavity to be drained by gravity into inspection chamber within the vault lobby. Cavity drainage system as Newton 508 membrane or similar to walls, soffit and floor. System to be drylined with plasterboard drylining system and painted white with floor screed and tiles above.





Take down and rebuild party fence wall complete from new foundations to existing height and profile reusing salvaged bricks in lime mortar.

