

Application No:	Consultees Name:	Received:	Comment:	Response:
-----------------	------------------	-----------	----------	-----------

2022/1485/L	Michael Dowd	10/06/2022 09:51:01	OBJ	
-------------	--------------	---------------------	-----	--

planning@camden.gov.uk

Retention of security light above main entrance  
Application no 2022/1485/L

#### OBJECTION

Two existing, discrete light fitting were recently removed by the applicant. See photograph attached. (An overhead light fitting, (B) and a fitting at the foot of the stairs (B)

The intention now is to replace these discrete existing fitting with aggressive 'motion activated', single, more powerful bulkhead fitting attached to the door frame.

This new single bulkhead light fitting has now been installed. The light from the bulkhead fitting is both too bright and the fitting and motion sensor inappropriate for this historic building, and is more appropriate to the High Street, not residential housing.

The new fitting with 'motion sensor' causes a severe nuisance to our ground floor bedroom, with 'on/off' sensors causing disturbance to bedroom occupants.

- Directly opposite the building is a street light which already adds to the security of the premises.this could be taken into consideration when assessing the external lighting needs.

#### PROPOSAL

If safety is the applicants concern, why have they removed the two existing handrails to the stairs? The handrails were recently removed and should be re-installed. ( the applicants' submission is misleading as it shows handrails! )These handrails were included in planning application ref: 2016/1286/P and are needed as a safety priority before blinding visitors with the proposed light fitting.

Removing existing two light fittings, and installing a single flood light pointed at visitors ( mostly the applicants airBnB guests ), using the staircase, without handrails which have been removed, is both reckless, intrusive and dangerous.

I ask that discrete fittings be installed, similar to existing ones removed.be installed, along with the replacement of the handrails, for safety..

/Users/michaedowd/Desktop/outside l.pdf