

Tree/ Group No.	Species	Approx Height (m)	Approx Stem Diam. at 1.5m (mm)	Approx Crown spread (m)	Age Class	Phys. Cond.	Condition	Management Recommendations 2022	Estimated Remaining Contribution (years)	BS 5837 Category Grading	Priority
									Assumed 2 man gang hours		
T240	Cedar (<i>Cedrus deodara</i>)	3.0	190	6	Semi-mature	Good	29.03.2019: No leader, but can develop. No work required. 13.03.2020: No work required. 18.03.2021: No work required. 05.07.2022: Dead.	Remove and grind stump to allow new planting.	>40	B2	Medium
T1	Honey locust (<i>Gleditsia triacanthos</i>)	8.0	150	8	Semi-mature	Good	18.3.21: Good form and vigour. 05.07.2022: Minor low deadwood. Extensive root damage caused by recent landscaping.	Remove minor deadwood.	>40	B	Low
T200	Cherry plum (<i>Prunus cerasifera</i>)	8.0	300	8	Mature	Fair	03.04.08: Multi-stem from base. Stem to northwest cracking and likely to fail. 13.03.09: Reduced during 2008, no further work required. 28.04.10: No work required. Consider further reduction during 2011. 28.04.11 No work required, consider further reduction during 2012. 03.04.12: Extensive fresh growth, putting stress on crack. 30.04.13: Crown reduced during 2012. 01.04.14: Crown reduced during 2013 - no further work required. 25.5.16 - Crown reduced since last inspection. 26.04.17: No work required. 12.03.18: No work required. 29.03.2019: At risk of splitting apart. 13.03.2020: reduced since last inspection. 18.03.2021: No work required.	Reduce height by approximately 2m and crown spread to balance, to reduce stress on weak forks.	10-20	C	Medium
T7	Oak (<i>Quercus robur</i>)	22.0	850	18	Mature	Fair	23.3.15: Minor deadwood. Subsidence concerns regarding property other side of Croft Way. Attractive tree. High amenity value. 25.5.16 - Crown reduced since last inspection. 26.04.17: Minor deadwood, but not large enough to present a risk- no work required. 12.03.18: No work required. 29.03.2019: Dense ivy to mid crown. Occasional deadwood, in particular over footpath. Branches hitting adjacent property. 13.03.2020: Deadwood removed and pruned from adjacent property since last inspection. 18.03.2021: Minor deadwood- too small to be a hazard. 05.07.2022: As above. Dense ivy to mid canopy.	Sever approximately 30% of ivy stems around base, to weaken, but not entirely kill ivy.	20-40	B	Low
G8	Buddleia	2.5		1.5	Mature	Fair	05.07.2022: Too close to buildings.	Cut to ground level.	5-10	C	Low
G202	5 no. Hornbeam (<i>Carpinus betulus</i>)	5.0 - 14.0	80 - 200	3.0 - 8.0	Middle aged	Fair	25.5.16 - 2 trees dead, remaining 5 showing reasonable vigour at present. 26.04.17: Two dead trees removed since last inspection- remaining 5 showing reasonable vigour. 12.03.18: No work required. 29.03.2019: No work required. 13.03.2020: No work required. 18.03.2021: No work required. Central tree has patches of dead basal bark. 05.07.2022: Central tree dead. Tree next to dead tree showing dieback.	Fell dead tree to ground level. Remove deadwood from adjacent tree.	10-20	C	Medium

15th July 2022

Tree/ Group No.	Species	Approx Height (m)	Approx Stem Diam. at 1.5m (mm)	Approx Crown spread (m)	Age Class	Phys. Cond.	Condition	Management Recommendations 2022	Estimated Remaining Contribution (years)	BS 5837 Category Grading	Priority
									Assumed 2 man gang hou		
T210	Cherry (<i>Prunus avium</i>)	10.5	230	10	Early mature	Good	30.04.13: Attractive tree, but with branches hitting building. 23.3.15: Pruned away from building during 2014. No work required. 25.5.16 - No work required. 26.04.17: Branches almost hitting adjacent building. 12.03.18: Pruned since last inspection. 29.03.2019: No work required. 13.03.2020: No work required. 18.03.2021: No work required. 05.07.2022: Canopy growing against roofs.	Reduce height by 1.5m and crown spread to balance, leaving at least 1m clearance to buildings.	15-30	B	Medium
G210	Undergrowth	2-6	25-100		Mature	Good	05.07.2022: Mixture of shrubs, thorn and hazel. Cutting out light to adjacent apartments.	Prune- reducing height by approximately 1.5m. Remove any dead shrubs.	10-20	C	Medium
T239	Mimosa (<i>Acacia dealbata</i>)	5.0	150	5	Semi- mature	Good	25.5.16 - Reasonable form structure and vigour. 26.04.17: No work required. 12.03.18: No work required. 29.03.2019: No work required. 13.03.2020: No work required. 18.03.2021: No work required. 05.07.2022: Only moderate vigour.	Reduce height by 2m and crown spread to balance. Remove deadwood.	15-30	B	Low
T37b	Pear (<i>Pyrus calleryana</i>)	8.0	180	2.5	Early mature	Fair	18.03.2021: Moderate vigour. 05.07.2022: Dense ivy to upper crown.	Remove section of ivy from base.	15-30	C	Medium
T39	Sycamore (<i>Acer pseudoplatanus</i>)	19.5	350	9	Middle aged	Fair	23.3.15: Consider crown reduction during 2016. 25.5.16 - Becoming over large for location. 26.04.17: Crown reduced since last inspection. 12.03.18: No work required. 29.03.2019: No work required. 13.03.2020: Ivy becoming rampant and blocking light. 18.03.2021: Ivy severed and basal stem removed. 05.07.2022: Becoming over large for location with lateral branches close to guttering.	Reduce height by 4m and crown spread towards buildings by 2m.	10-20	C	Medium
T42	Sycamore (<i>Acer pseudoplatanus</i>)	19.5	700	9	Mature	Fair	26.04.17: Crown reduced since last inspection. 12.03.18: No work required. 29.03.2019: No work required. 18.03.2021: Ivy severed. 05.07.2022: Becoming overlarge for location close to buildings.	Reduce height by 4m and crown spread	10-20	C	Medium
G212	2no Cotoneaster (<i>Cotoneaster simonsii</i>)	6.0	90	5	Mature	Fair	01.04.14: Branches from both hitting building. 23.3.15: Pruned during 2014. 25.5.16 - No work required. 26.04.17: No work required. 12.03.18: No work required. 29.03.2019: No work required. 13.03.2020: Becoming leggy and blocking light to 1st floor windows. 18.03.2021: Pruned since last inspection.	Reduce height by 1.5m.	10-20	C	Medium
G225	2no Cotoneaster (<i>Cotoneaster simonsii</i>)	5.0	150	5	Early mature	Fair	25.5.16 - Stems growing out towards building. 26.04.17: Pruned since last inspection. 12.03.18: No work required. 29.03.2019: No work required. 18.03.2021: Pruned since last inspection.	Reduce height by 2m.	10-20	C	Medium

15th July 2022

Tree/ Group No.	Species	Approx Height (m)	Approx Stem Diam. at 1.5m (mm)	Approx Crown spread (m)	Age Class	Phys. Cond.	Condition	Management Recommendations 2022	Estimated Remaining Contribution (years)	BS 5837 Category Grading	Priority
									Assumed 2 man gang hours		
T67	Lime (<i>Tilia x europaea</i>)	20.0	700	12	Mature	Good	25.5.16: As above. 26.04.17: Still showing reasonable vigour, despite basal decay. 12.03.18: No work required. 29.03.2019: No work required. 13.03.2020: Dead branches over compost area. 18.03.2021: No work required. 05.07.2022: Deadwood.	Remove deadwood. Reduce height by 3m.	20-40	A	Medium
T66	Lime (<i>Tilia x europaea</i>)	20.0	650	9	Mature	Fair	25.5.16: No work required. 26.04.17: No work required. 12.03.18: No work required. 29.03.2019: Dense ivy to mid canopy. 13.03.2020: Good vigour. 18.03.2021: No work required. 05.07.2022: Remove section of ivy from base.	Remove deadwood. Reduce height by 3m.	20-40	B	Medium
T108a	Hombeam	7.0	140	6	Semi-mature			Remove.	<10	U	Medium
T106	Horse chestnut (<i>Aesculus hippocastanum</i>)	24.0	1400	20	Mature	Fair	23.3.15: Patch of decay at base to west, but showing good vitality. 25.5.16 - patches of basal decay to north and west. Internal decay test undertaken, showing only localised decay. 26.04.17: Showing good vigour no work required. 12.03.18: No work required. 29.03.2019: Some increase in basal decay, with immature white bulbous fungal fruiting body at base to north. Showing good vigour. 13.03.2020: White bulbous fungal brackets- probably <i>Ganoderma</i> sp. - found at various points around base. Approximately 100mm decay at base to west. Decay entering pruning wounds. 18.03.2021: Decay as above- no significant development. Canopy maintaining good vigour. 05.07.2022: Further decay as above. Leaf minor infestation.	Carry out 20% crown reduction as indicated on photo included as Appendix F.	10-20	B	
T101	Birch (<i>Betula pendula</i>)	16.0	300	9	Mature	Good	03.04.12: Good form and structure. Attractive tree. 30.04.13: No work required. 01.04.14: No work required. 23.3.15: No work required. 25.5.16 - No work required. 26.04.17: No work required. 12.03.18: No work required. 29.03.2019: No work required. 13.03.2020: No work required. 18.03.2021: No work required. 05.07.2022: Dead.	Remove and grind stump.	20-40	B	Medium
G97	Shrubs	3.5					05.07.2022: Becoming too large to maintain.	Reduce height by 1.5m.	5-10	C	Low
T236	Mimosa (<i>Acacia dealbata</i>)	5.5	150	6	Semi-mature	Good	01.04.14: Growing strongly. Consider pruning during 2015 - no work required. 23.3.15: Pruned during 2014. No work required. 25.5.16 -No work required. 26.04.17: Very rapid growth- beginning intrude on balcony. 12.03.18: Crown reduced since last inspection. 29.03.2019: No work required. 13.03.2020: Rampant growth. 18.03.2021: Crown reduced since last inspection. 05.07.2022: growing vigorously	Reduce height by 2m and crown spread to balance.	20-40	B	Medium

15th July 2022