

GENERAL NOTES:

- 1. Refurbished external door
- 2. Existing lift refurbished
- 3. All doors to be retained and redecorated. Where appropriate and in accordance with fire consultant specification treat with envirograf fire coating.
- 4. New kitchenette

New wiring and sockets to be proposed

boxes. See MEP consultant details.

underneath existing plywood flooring in floor

- 5. New electric radiators as indicated
- 6. New slate effect hearth
- 7. Existing stairs refurbished with new carpet.
- 8. Areas of damaged lath and plaster repaired, re-plastered and redecorated.
- Existing damaged and missing suspended ceiling to be carefully removed and replaced
- 10. All existing windows to be refurbished and to receive new ironmongery
- 11. Existing WCs fully refurbished with new sanitary wear
- Any existing damaged or missing areas of plasterboard with skim finish repaired and redecorated
- Existing cast iron fireplace and wood surround retained and refurbished. Existing decorated wood surround stripped back and redecorated
- 14. New downlights in basement
- 15. Existing fireplace hearth and surround retained. Existing decorated surround stripped back and redecorated
- 16. All existing window boards and reveals retained, stripped back and redecorated
- 17. Existing stone surrounds retained and cleaned
- 18. Existing painted balustrade redecorated
- 19. New stair tread installed to match existing stairs
- 20. Existing stairs walls repaired ready for redecoration
- 21. All existing wall and ceiling lights to be replaced. Existing locations to be utilised to avoid further intervention with historic building fabric.
- 22. All existing trunking and conduits to be retained 23. All previously infilled openings between 17 and 18 are to be reviewed and upgraded to provide 60min fire separation between buildings, from the no.18 side, to be
- confirmed by building control 24. All ceiling rose to be retained and redecorated
- All mouldings, skirtings, dado railing and paneling to be repainted and made good where damaged.
- 26. All areas of water ingress/damp to be properly inspected and repaired.
- 27. Replace All FCU's in existing locations.
- 28. Existing window and door to be fitted with automatic opener as AOV

Scale 1:50 *****

2ND FLOOR - GENERAL ARRANGEMENT

All dimensions must be checked on site and NOT scaled from this drawing. SUBJECT TO SITE SURVEY CHECK SURVEY UNDERTAKEN ONLY BUILDING PARAMETERS TAKEN FROM DRAWINGS PROVIDED BUILDING PARAMETERS TAKEN FROM

AS BUILT DRAWINGS PROVIDED

This drawing is protected under Copyright and at no time must any portion of this drawing be reproduced or copied

in anyway without the permission of Morgan Lovell.

					l
					l
					l
					l
					Ì
					l
					l
P1	FIRST ISSUE FOR REVIEW	JPF	TC	09.06.22	
Rev	Revision	Ву	Ckd	Date	

Morgan Lovell

16 Noel Street London W1F 8DA T: 0207 734 4466 F: 0207 734 2968 E: contact@morganlovell.com **W**: http://www.morganlovell.com

Hogarth Properties (Rothschild) PROJECT 04

18 & 19 SOUTHAMPTON PLACE

FOR PLANNING 2ND FLOOR **GENERAL ARRANGEMENT** 1:50 @ A1 NOV.21 TC / JPF

Drawing Number Project No. ML3953 02 706