



Existing door opening into vault.

Existing historic black painted metal fence and service gate.
Existing timber post.
Existing timber service stairs in front lightwell (dotted for reference), in poor condition.




Existing historic black painted metal fence and service gate.
Existing timber service stairs in poor condition.

- GENERAL NOTES**
- Read all drawings in conjunction with associated specification, schedules and documents.
 - Read all the notes on this drawing.
 - Based on survey information by others.
 - Drawing's level of detail not suitable for construction.
 - Contractor to check and confirm dimensions on site.
 - All fire ratings and new works subject to Building Control approval.




01 Fence Elevation - As Existing
3600 1:50 @ A3

03 Section Through Lightwell - As Existing
3600 1:50 @ A3




Existing timber service stairs in poor condition.
Existing historic black painted metal fence and service gate.



04 Existing timber stairs - photo
3600 NTS

00 Key Plan
3600 1:200 @ A3

Purpose of Issue:
FOR CONSTRUCTION



02 Ground Floor Plan - As Existing
3600 1:50 @ A3

Notes

1. Any dwg format drawing is to be read in conjunction with and at the scale of the accompanying pdf.
2. Where colours other than black or grey are used, the drawing must be plotted in colour.
3. For status 'C' (Construction) drawings all dimensions are to be checked on site by the contractor, scaling is for Local Authority purposes only.
4. Unless otherwise indicated, all dimensions are in millimeters.
5. All information on this drawing is to be read in conjunction with the relevant Donald Insall Associates specification and trade contractors' drawings and information by specialists.
6. In the event of any discrepancy, please contact us immediately.
7. This drawing may contain survey information by others and is to be used solely for the purposes for which it was issued.
8. These are uncontrolled documents issued for information purposes only. If you have any queries regarding the drawings, please contact DIA immediately.
9. Please note DIA cannot be held responsible for any errors arising from changes made to an uncontrolled dwg file.

© 2019 DONALD INSALL ASSOCIATES LTD

Drawing Status		Rev		Date		Dwn		Auth		Revision	
F	Feasibility										
S	Sketch Design										
P	Planning										
B	Building Control										
D	Design Development										
M	Measurement										
T	Tender										
C	Construction										
R	Record										
		0	21-10-22	MXV	RD					Issued for Discharge of Condition	
		Rev	Date	Dwn	Auth	Revision					

Donald Insall Associates
Chartered Architects and Historic Building Consultants

12 Devonshire Street
London W1G 7AB
(+44) 020 7245 9888
london@insall-architects.co.uk

25 John Street, London

External Service Stairs to Lightwell As Existing	Project JSC25.01 Scale (A3) 1:50	No 3600 Status 5C Revision 0
---	---	---