Apart from staircase fire-resisting structures, all sub compartment fire resistance shown on plans is structurally in place but may be broached by air conditioning ductwork, plenums and vents & are not fitted with fire resisting dampers



