
iron beams, including embedded ends



VIEW 1

Contractor to allow for temporarily diverting services in order to carry out repairs to cast iron beams

(1:20)

Damp walls to be repainted as required by Architect



VIEW 2

1. This drawing is to be read in conjunction with all relevant Architect's and Engineer's drawings and the specification.

NOT FOR CONSTRUCTION

Α	10.02.23	ISSUED FOR LISTED BUILDING CONSENT	MSp
-	22.02.22	ISSUED FOR TENDER	LK

British Museum Phase 6 Fabric Repairs Staircases

Repairs to Stair 2

checked AEs LK scale (original - A3) January 2022 1:20

Alan Baxter

75 Cowcross Street London EC1M 6EL tel 020 7250 1555 email aba@alanbaxter.co.uk

www.alanbaxter.co.uk

1910/20/03

Alan Baxter Ltd is a limited company registered in England and Wales, number 06600598. Registered office as above.