

W.03.04

NOTES :

Modern casement
Post condition

Modern casement window.
Lowest significance.
No other detailing.
No related detail of interest.
Non original
dormer (widened pre-existing).



W.02.06

NOTES :

Weighted sash
6 panel sashes
Manually operated blinds shut

Original 6x6 casement sash window. Highest significance.
Simple detailing to panelled shutters and panel beneath window reflecting hierarchy of the original house. Shutters fixed shut and overpainted with signs of repair and filling.
Reasonable condition. Highest significance.



W.01.06

NOTES :

Weighted sash
6 over 9 panel sashes
Shutters historic and probably original
Painted sash
Manually operated blinds
Pipework through panel

Fixed shut and painted over shutter boxes in squared reveals and distinct from those to no. 34. Poor condition of LHS and bad repairs indicative of previous opening up and disruption.
Highest significance.
Windows have no horns and appear to be original to the building although the glazing is later and sources record that the windows of the first floor were blown out (including glazing bars) during WWII. Given the importance of the first floor windows and appropriate detailing these are considered to be of the highest significance.



XD.00.02

NOTES :

Original doorway to number 35
Fixed 12 panel window with side lights
Ornate toplight maybe original
Manually operated blinds





Original door and historic side lights of no. 35 removed in 1919 and replaced with window. Original fanlight retained. Fanlight of the highest significance.
Door and side lights low to medium significance as while they relate to overall character, the window reduces the legibility of the original house and is of less value in terms of its fabric.



D.B1.10

NOTES :


1920s door with roller shutter.
Medium significance.



Rev	Date	Description	Author	Checker

Scale at A1 / A3

1:25 / 1:50



Drawing Name
Existing Internal Elevations Window Stack 04

Drawing Number Revision
BW125 - BW - ## - XX - DR - E3004