

original dividing (party) wall to adjoining house - existing Roman cement in-situ run cornice over terracotta creasing tiles evidence original coping provision to wall

portland cement moulding to match original re-run with swept detail to connect original coping level to reduced wall height. Roman cement band on adjoining property side aligns with saltaire detailed wall on opposite corner of Inverness Street/Gloucester Crescent junction

Portland cement moulding and swept curve removed





image of adjoining property saltire wall showing open block - foriginal errous reinforcement creating spalling caused by water penetration/lack of maintenance

arts lettres techniques ARCHITECT Arts Lettres Techniques Limited 2022 copyright is retained ©

33A ARLINGTON ROAD LONDON NW1 7ES T: (020) 7383 4778 architect@artslettres.com

ALL DIMENSIONS MUST BE VERIFIED ON SITE

PROJECT 23 Gloucester crescent NUMBER GC 604 SCALE 1:50/1:5 @ A2

SUBJECT Section AA + details proposed REVISION A DATE 01/05/22

revisions

A 07.06.2022 additional detail

scale 1:50 1.0m 5.0m