

MAIN ENTRANCE - SECTION



MAIN ENTRANCE - ELEVATION



STAIR TYPICAL TREAD/RISER DETAIL



MAIN ENTRANCE - PLAN

Keyplan

North

Notes:
1. Do not scale
2. Contractor to Check all dimensions and report omissions and errors to the Architect

No	Revision	Date	Initial	Chkd
A	CONSTRUCTION ISSUE	25.07.16	MG	
03	Main Entrance steps and sesame lift updated following workshop meeting	07.07.16	DB	
02	Sesame access setting out and stairs updated for co-ordination purposes	29.06.16	DB	
01	TENDER 2	24.03.16	MG	

GENERAL NOTES:

1. THIS DRAWING TO BE READ IN CONJUNCTION WITH EPR ARCHITECTS SPECIFICATION 10089-5-00-0001-ZXX
2. THIS DRAWING TO BE READ IN CONJUNCTION WITH EPR SCHEDULES AND WORKS DOCUMENT & EPR ELEVATIONS (DRG SERIES 0400)
3. THIS DRAWING TO BE READ IN CONJUNCTION WITH HARRISON GOLDMAN EXTERNAL FACADE CONDITION SURVEY - COLUMNS AND PLINTHS
4. FOR STRUCTURAL DETAILS FOR TERRACE SUPPORTING STRUCTURE REFER TO STRUCTURAL ENGINEER'S DRAWINGS
5. THIS DRAWING TO BE READ IN CONJUNCTION WITH LANDSCAPE CONSULTANT AND LIGHTING DESIGNER'S DRAWINGS AND SCHEDULES

NOTE 1: CEMENTITIOUS SLURRY DPM SYSTEM TIED AND LAPPED INTO EXISTING SUBSTRATE PRIOR TO BEDDING AND NEW STONE FINISH. WATERBAR OR ACCESSORIES AS REQUIRED TO SUIT EXISTING BUILDING FABRIC DETERMINED AFTER STRIP-OUT. ASSUMED LEVELING SCREED REQUIRED TO EXISTING SLAB

EPR architects
30 Millbank
London SW1P 4DU
+44 (0) 20 7932 7600
www.epr.co.uk

Russell Hotel
Camden

Main Entrance
External Stair Details

CONSTRUCTION 1: 20 @ A1 29.05.15

Project No	Type	Blg	Number	Zone/Lvl	Rev
10089	4	01	9041	ZXX	A

R:\10089\Plan\Chest\0400-ExternalWorks_General\10089-4-01-9041-ZXX.dgn 25/07/2016