


Ξ	MEANS OF WAR	NING
MANDATORY SIGN (FIRE DOOR KEEP LOCKED SHUT), SIGNAGE TO MEET RECOMMENDATION OF BS5499-PART 5 MANDATORY SIGN "BOTH SIDES" (FIRE DOOR	LD1	APARTMENT WITH OPEN-PLAN LAYOUT. APARTMENT PROVIDED WITH FIRE ALARM AND DETECTION SYSTEM IN ACCORDANCE WITH BS5839 PART 6
KEEP SHUT), SIGNAGE TO MEET RECOMMENDATION OF BS5499-PART 5	SC	DOOR(S) TO BE PROVIDED WITH POSITIVE SELF CLOSING DEVICE(S) AND SIGNS TO BOTH FACES WORDED "FIRE DOOR - KEEP
MANDATORY SIGN "BOTH SIDES" (AUTOMATIC FIRE DOOR KEEP CLEAR), SIGNAGE TO MEET RECOMMENDATION OF BS5499-PART 5		SHUT" IN WHITE LETTERING ON BLUE BACKGROUND
SAFE CONDITION SIGN-GREEN (FIRE EXIT) WITH ARROW UP, SIGNAGE TO MEET RECOMMENDATION OF BS5499-PART 4. POWER ILLUMINATED	VP	VISION PANEL OF CLEAR FIRE RESISTING GLAZING TO BE PROVIDED IN A FIRE RESISTING DOOR OR PARTITION. THE PERIOD OF FIRE RESISTANCE TO BE APPROPRIATE TO THE FIRE RESISTANCE OF THE DOOR/PARTITION IN WHICH IT IS FIXED.
SAFE CONDITION SIGN-GREEN (FIRE EXIT) WITH ARROW LEFT-RIGHT (DOUBLE SIDED SIGN), SIGNAGE TO MEET RECOMMENDATION OF BS5499-PART 4. POWER ILLUMINATED		
SAFE CONDITION SIGN-GREEN (FIRE EXIT) WITH MAN UP/DOWN AND ARROW LEFT-RIGHT (DOUBLE SIDED SIGN) SIGNAGE TO MEET RECOMMENDATION OF BS5499-PART4. PHOTO LUMINESCENT		



DO NOT SCALE DIMENSIONS OF THIS DRAWING. CHECK ALL DIMENSIONS ON SITE BEFORE FABRICATION. FINAL COORDINATION AND CHECKS ARE RESPONSIBILITY OF THE SITE TEAM TO SUIT CONDITIONS AND TOLERANCES BEFORE ANY INSTALATION. REPORT ALL ERRORS OR OMISSIONS TO MIDGARD LIMITED. THIS DRAWING IS PROTECTED UNDER COPYRIGHT AND SHALL NOT BE REPRODUCED IN PART OR WHOLE WITHOUT PRIOR EXPRESSED PERMISSION OF MIDGARD LIMITED.

KEY PLAN



GENERAL NOTES

- THIS DRAWING SHOULD BE READ IN CONJUNCTION WITH FIRE CONSULTANTS **REPORTS & SPECIFICATIONS**

- EMERGENCY LIGHTING DESIGN TO MEET BS5266 REQUIREMENTS IN LINE WITH FIRE CONSULTANTS FIRE STRATEGY REPORT & M&E CONSULTANTS **REPORTS & SPECIFICATIONS**

- FIRE ALARMS, SOUNDERS, SMOKE & HEAT DETECTORS TO BE IN ACCORDANCE WITH FIRE & M&E CONSULTANTS REPORTS & SPECIFICATIONS

- CAVITY BARRIERS REQUIRED AROUND **OPENINGS & COMPARTMENT LINE LOCATIONS**

- SPRINKLERS WITHIN APARTMENTS TO BE DESIGNED & INSTALLED IN ACCORDANCE WITH SPRINKLER SUBCONTRACTORS DRAWINGS & SPECIFICATIONS

MEANS OF DETECTION AND WARNING:

- LD1: All flats incorporate open-plan layouts, therefore a Grade D2 LD1 fire alarm and fire detection system in accordance with BS 5839-6:2019 is to be installed

-L2: An L2 detection and alarm system, in line with the recommendations of BS 5839-1:2017, is provided throughout W0.

The retail unit alarm systems will be provided as part of the fit out for the units. An L2 detection and alarm system, in accordance with BS 5839-1:2017 should be provided in the retail units as a minimum.

Due to the potential for sleeping occupants in the creche, it is recommended that an L2 detection and alarm system, in line with the recommendations of BS 5839-1:2017, is provided throughout W3.

-L5: The common corridors within the residential accommodations and communal areas at Ground Floor of W1 incorporate an L5 fire detection and alarm system in accordance with BS 5839-1:2017.

-Sounders to conform with BS 5839-1 requirements.

C04	AV	02.02.23	AM	UPDATES TO FIRE STRATEGY PLANS
C03	AV	31.01.23	AM	FIRE SIGNAGE LEGEND REVISED / FIRE SIGNS UPDATED / FIRE ESCAPE ROUTES UPDATED
C02	ID	05.01.23	AM	LAYOUT GENERALLY ADJUSTED / MDS COMMENTS APPLIED / DRAWING TITLE UPDATED AS PER PROTOCOL
C01	VS	16.11.21	AM	GENERAL NOTES UPDATED / MINOR AMENDMENTS
P01	BH	26.10.21	AM	FIRST ISSUE FOR STAGE 5 / GENERAL AMENDMENTS
REV	ΒY	DATE	СНК	DESCRIPTION
STAT	US			

FOR CONSTRUCTION

CONTRACTOR

Midgard Ltd

PROJECT

King's Cross Central Zone W

CLIENT

Argent LLP

DRAWING TITLE Block W0 - Fire Strategy Ground Floor - Part B

10.03.20	02.02.23	1 : 100 @A1
DRAWN BY	AMENDED BY	CHECKED AM

KXC-TRI-W0-001-A-MDS060-20-9GFB-C04

