belong to Baily Garner LLP and may only be used in accordance with the licence granted to the Employer and with attribution to Baily Garner LLP. The drawing to be read in conjunction with:Document Suitability Codes page or at Elevation 1 Elevation 2 **KEY** WINDOWS TO BE RETAINED **CONCRETE WALL ICT** ART 3 ROOF AREA TO BE REPLACED 150MM UPSTAND TO WINDOW AND DOOR CILLS **INFORMATION** 1. ABOVE EXISTING CORRIDOR DOOR ALLOW FOR REMOVAL AND RELOCATION OF EXISTING SERVICES PENETRATING FRAME 2. TO ART1-3 AND ICT 1 ALLOW FOR ADAPTATIONS TO EXISTING **SERVICES** 3. REMOVAL OF CORRIDOR DOOR TO BE REPLACED WITH A WINDOW. RAISE DOOR AND WINDOW CILLS TO CREATE A MINIMUM UPSTAND OF 150MM AS PER BAUDER SPEC. 5. REMOVAL OF EXISTING FAN LIGHT WINDOWS TO ACHIEVE Connection MINIMUM UPSTAND AND Connection Connection Connection MAINTAIN REASONABLE DOOR Line 5 HEIGHTS. Line 2 Line 1 Line 1 London Borough of Camden Roof And Window Proposed Elevations BAILY GARNER Refurbishment Works **Acland Burghley Proposed Elevations** Acland Burghley - Roof and Window Refurbishment Works Tender

The contractor is responsible to ensure that no products are to be utilised that do not comply with relevant British and/or European Standards and/or Codes of Practice, COSHH Regulation Construction Regulations, or which are known or suspected at the time of product selection and/or construction to be deleterious to health and safety or to the durability of the work or not

The contractor is responsible for checking dimensions, tolerances, levels and references. This drawing/model is to be read in conjunction with all relevant Other Project Team Members' or specialists' drawings/models/any Federated Model. Any discrepancy is to be notified to Baily Garner LLP and is to be rectified before proceeding with the works on site or shop drawings.

Any rights (including copyright) in this drawing/model and any proprietary work contained therein

146-148 ELTHAM HILL LONDON SE9 5DY

accordance with good building practices.