

The contractor is responsible to ensure that no products are to be utilised that do not comply with relevant British and/or European Standards and/or Codes of Practice, COSHH Regulation Construction Regulations, or which are known or suspected at the time of product selection and/or construction to be deleterious to health and safety or to the durability of the work or not accordance with good building practices.

The contractor is responsible for checking dimensions, tolerances, levels and references. This drawing/model is to be read in conjunction with all relevant Other Project Team Members' or specialists' drawings/models/any Federated Model. Any discrepancy is to be notified to Baily Garner LLP and is to be rectified before proceeding with the works on site or shop drawings.

Any rights (including copyright) in this drawing/model and any proprietary work contained therein belong to Baily Garner LLP and may only be used in accordance with the licence granted to the Employer and with attribution to Baily Garner LLP.

The drawing to be read in conjunction with:Document Suitability Codes page or at

KEY

WINDOWS TO BE RETAINED



CONCRETE WALL



ROOF AREA TO BE REPLACED



150MM UPSTAND TO WINDOW AND DOOR CILLS

INFORMATION

- ABOVE EXISTING CORRIDOR DOOR ALLOW FOR REMOVAL AND RELOCATION OF EXISTING SERVICES PENETRATING FRAME.
- 2. TO ART1-3 AND ICT 1 ALLOW FOR ADAPTATIONS TO EXISTING **SERVICES**
- 3. REMOVAL OF CORRIDOR DOOR TO BE REPLACED WITH A WINDOW.
- RAISE DOOR AND WINDOW CILLS TO CREATE A MINIMUM UPSTAND OF 150MM AS PER BAUDER SPEC.
- REMOVAL OF EXISTING FAN LIGHT WINDOWS TO ACHIEVE MINIMUM UPSTAND AND MAINTAIN REASONABLE DOOR HEIGHTS.

Proposed Elevations

Acland Burghley - Roof and Window Refurbishment Works

London Borough of Camden

Acland Burghley

Roof And Window Refurbishment Works **Existing Elevations**

Tender



146-148 ELTHAM HILL LONDON SE9 5DY