

Application No:	Consultees Name:	Received:	Comment:	Response:
2023/2435/P	Dean la Tourelle	02/07/2023 15:45:17	INT	<p>Roof</p> <p>Flat roof raised by 200mm: unacceptable, the raised roof would be unlike any other roof in the Conservation Area and an unwanted feature in the roofscape.</p> <p>Front sloping roof roof light: unacceptable, roof lights on the front slope of a roof in the Conservation Area should never be approved.</p> <p>Side stair rooflight: unacceptable, the large roof light would be very intrusive in the Conservation Area.</p> <p>Large rear dormer: unacceptable, very intrusive and much larger than other neighbouring roof alterations.</p> <p>Interior</p> <p>The central space has inadequate light, ventilation and view, the bathroom is not useable and the rear space depends on an unacceptable dormer.</p> <p>Conclusion</p> <p>The application should be refused.</p>
2023/2435/P	Dean la Tourelle	02/07/2023 15:45:31	INT	<p>Roof</p> <p>Flat roof raised by 200mm: unacceptable, the raised roof would be unlike any other roof in the Conservation Area and an unwanted feature in the roofscape.</p> <p>Front sloping roof roof light: unacceptable, roof lights on the front slope of a roof in the Conservation Area should never be approved.</p> <p>Side stair rooflight: unacceptable, the large roof light would be very intrusive in the Conservation Area.</p> <p>Large rear dormer: unacceptable, very intrusive and much larger than other neighbouring roof alterations.</p> <p>Interior</p> <p>The central space has inadequate light, ventilation and view, the bathroom is not useable and the rear space depends on an unacceptable dormer.</p> <p>Conclusion</p> <p>The application should be refused.</p>
2023/2435/P	Dean la Tourelle	02/07/2023 15:45:39	INT	<p>Roof</p> <p>Flat roof raised by 200mm: unacceptable, the raised roof would be unlike any other roof in the Conservation Area and an unwanted feature in the roofscape.</p> <p>Front sloping roof roof light: unacceptable, roof lights on the front slope of a roof in the Conservation Area should never be approved.</p> <p>Side stair rooflight: unacceptable, the large roof light would be very intrusive in the Conservation Area.</p> <p>Large rear dormer: unacceptable, very intrusive and much larger than other neighbouring roof alterations.</p> <p>Interior</p> <p>The central space has inadequate light, ventilation and view, the bathroom is not useable and the rear space depends on an unacceptable dormer.</p> <p>Conclusion</p> <p>The application should be refused.</p>