

	Strip Out Key		
	ALT-111Removal of Internal Non-Structural Masonry WallsALT-112Removal of Internal PVC WallsALT-113Removal of Internal Plasterboard PartitionALT-115Removal of Internal Plasterboard Linings to Solid WallsALT-119Removal of Internal Plasterboard Linings to Solid WallsALT-119Removal of Internal Plasterboard Linings to Solid WallsALT-119Removal of Internal Vall Linings to Concealed Fireplace/Chimney breastALT-131Removal of Non-Thermally-Improving Secondary GlazingALT-133Removal of Internal DoorsetsALT-136Removal of Wall Access PanelsALT-137Removal of Wall PanelALT-138Removal of Roof HatchALT-143Removal of Kitchen FittingsALT-145Removal of SanitarywareALT-152Removal of External Glazed Roof LightALT-152Removal of Flat Roof WaterproofingALT-906Form Opening in Internal CeilingALT-907Modify Ceiling Hatch OpeningRadiators to be retained until Client sign off		
	ALT-103       Removal of Internal Suspended Ceiling Tile System         ALT-107       Removal of Internal Ceiling Coverings (Ceiling Wallpaper)         ALT-142       Removal of Window Blinds         ALT-146       Removal of Curtain Tracks         ALT-148       Removal of Perimeter Trunking         ALT-149       Removal of Signage - Statutory and Non-statutory         ALT-123       Removal of Internal Floor Build-up         ALT-125       Removal of Internal Floor Screed		
	ALT-129 Removal of Internal Timber Skirting ALT-121 Removal of Internal Floor Covering ALT-107 Removal of Internal Ceiling Coverings (Ceiling Wallpaper) ALT-142 Removal of Window Blinds ALT-146 Removal of Curtain Track ALT-148 Removal of Peremeter Trunking ALT-149 Removal of Signage - Statutory and Non-Statutory		
	Historic elements to be striped by Specialist Contractor. Refer to the Restoration drawings for retained doorsets to be refurbished. ALT-101 Removal of Internal Ceiling Cornice Moulding ALT-135 Removal of Internal Doorsets ALT-147 Removal of Radiator Cover		
To all surfaces			
as applicable	Operational area to be maintained and protected throughout works.		
*	MOE doors to be retained. Door required for fire integrity to be stripped out by Main Contractor		
	Existing walls/structure to remain.		
	Not in Scope.		
• Retain all wal • Retain ceiling • Retain lath ar	Elements to Retain: <ul> <li>Retain all wall mouldings, chair rails.</li> <li>Retain ceiling cornices where these adjoin downstand beams or walls.</li> <li>Retain lath and plaster ceiling.</li> <li>Temporary retain radiators, until client sign off</li> </ul>		
Unprotected N Design measu • Guarding to a • At least one occupants. Information P • Strip out draw	Demolition and Strip-Out Risk Elimination Notes:         Unprotected Voids         Design measures taken to reduce / eliminate risk         • Guarding to all service voids and lift doors to be provided by the contractor.         • At least one of the lift should remain operational during the whole of strip out period for occupants.         Information Provided for Hazard Control         • Strip out drawings showing riser locations assumed from archive drawings.		
• Temporary gu Information P	Design measures taken to reduce / eliminate risk • Temporary guarding to all unprotected roof edges required. Information Provided for Hazard Control • Strip out drawings identify unprotected roof edges.		
Information P • Strip out draw Operational P Design measu • Services to bu to strip out. Information P	Fire Escape Information Provided for Hazard Control • Strip out drawings identify escape route to be maintained at all times. Operational Premises Design measures taken to reduce / eliminate risk • Services to be retained / power supplies to be maintained to be identified prior to strip out. Information Provided for Hazard Control • L4 will remain operational during the whole of the strip out period.		
Information P     Tight urban si     during the work     Asbestos			
Management     Refurbishmer     any works.     Information Pro	Design measures taken to reduce / eliminate risk • Management Asbestos Survey information issued with tender. • Refurbishment Asbestos Survey to be carried out by strip out contractor prior to		
<ul> <li>See M+E Ser</li> <li>Read in conju</li> <li>Refer to the S</li> <li>Ensure stair a</li> <li>Specialist cor</li> <li>All existing W</li> <li>To be read in</li> </ul>	Notes:         • All existing windows to be retained and protected during works.         • See M+E Services Engineers Scope, Drawings and Specification for services strip out.         • Read in conjunction with BNP's Site Inspection Report         • Refer to the Structural Engineer prior to removing any masonry walls         • Ensure stair and lift cores fire compartmentation is maintained throughout works.         • Specialist contractor to assess perimeter walls mould/ moisture         • All existing Windows to be retained and to be protected during works         • To be read in conjunction with JRA specifications         • To be read in conjunction with Structural Engineers' information and requirements		

Tavistock House

British Medical Association BMA House, Tavistock Square London WC1H 9JP 0300 123 1233 IBeach@bma.org.uk

0	1	2	3	4	5	10m

## Drawing Title Block F & G - Fourth Floor Strip-Out Plan

Scale	1:100 @ A0	Internal Project No. 1998			
Dwg No.	1998-JRA-02-04-DR-A-0068				
Suitability	WORK IN PROGRESS	S SO			
Revision	PRELIMINARY	P01			