

08.Not used

02.Not used

09. Existing metal railings refurbished and redecorated

10. Proposed built in joinery

finishes to match existing

- 11. Existing chimney piece to be refurbished and redecorated where
- 12. Proposed column radiator
- 13. Existing slates removed and re-laid with any damaged or defective replaced to match existing
- 14.All roof flashings to be replaced

accompanying approved scheme

accompanying approved scheme

- 15.Not used 16-Proposed service riser
- 17.Not used
- 18.Contemporary timber staircase
- 19.Infill partition, wall build up to match adjacent wall
- 20.Not used
- 21. Proposed chimney piece and hearth
- 22. Proposed shower tray over existing floorboards
- 23.Replacement partition wall
- 24.New partition wall
- 25.Proposed bi-folding frosted glass screen to window 26.Proposed dormer windows to match No.7
- 27. Existing roof tiles to be removed and re-laid, and defective tiles to be replaced to match existing
- 28.All roof flashings to be replaced
- 29.Not used
- 30.Rainwater pipes and gutters to be replaced with heritage cast
- 31.Reinstatement of existing sash window in 6 over 6 configuration 32. Existing sash window to be removed and replaced with a traditionally detailed timber sash window with 3 over 3 configuration
- 33.New Conservation rooflight 34.Not Used
- 35.Not used 36.Not used
- 37.Not used
- 38.New timber framed dormer windows with 3 over 3 configuration

- FLOORING FINISHES
- FLOOR 1: Specified floor finish over water fed floor heating over existing slab
- FLOOR 2: Specified floor finish over electric floor heating over existing slab
- FLOOR 3: Specified floor finish on existing structural slab
- FLOOR 4: Specified floor finish on existing levelled floor joists. Insulation fitted
- FLOOR 5: Specified floor finish on electric underfloor heating mat on ply over existing floorboards on levelled floor joists. Insulation fitted between

FLOOR 6: Specified floor finish on existing levelled floor joists with wet underfloor heating trays and insulation fitted between

## **GENERAL NOTES**

- 1. Existing brickwork to be repaired and repointed throughout
- 2.Retain and refurbish all window boxes architraves and shutters 3.All original skirtings to be removed, refurbished and reinstated. Where new skirtings are proposed, refer to drawing approved scheme drawing A6900
- 4.All cornices to be refurbished and repaired where necessary. Where new cornices are proposed refer to approved scheme drawing A6900
- 5.All existing walls and ceilings to be locally re-skimmed and painted as required
- 6. Where new partitions are shown, existing skirtings/cornice to be match existing profile to be carefully pieced in.



Copyright Reserved ©

20.12.22

PLO4

D

DATE REVISIONS OTTER HUT, THE QUAY, BURNHAM-ON-CROUCH, ESSEX CMO 8AX TEL: 0 | 62 | 782002 FAX: 0 | 62 | 786002 8 GREAT JAMES STREET 1:50 @ A3 LONDON WCI PROPOSED SECOND FLOOR PLAN 2209

REVISION NO. ADDED

ANNOTATION ADDED

BEDROOM I CUPID & DOOR RETAILIED

30 .8 . 2023 D

C

25.8.2023

18.4.2023