Replacement GGL-8 X 35 PVC frame Split in two quotations: 16 within reach - (manual blinds) 19 high elevation - (motorized blinds) Window 1 804 Window 2 Window 3 Window 4 804 804 804 S/C B/US S/C B/US S/C B/US S/C PB FRONT OFFICE CORNER OFFICE 3 Window 5 804 S/C B/US SIDE OFFICE 1 Window 6 Vindow 20 Window 2 808 S/C B/US SIDE OFFICE 2 CORNER OFFICE 2 CORNER OFFICE 1 REAR OFFICE SMALL OFFICE 1 SMALL OFFICE 2