



EXISTING RIBBED METAL ROOF IN POOR STATE OF REPAIR

EXISTING DILAPIDATED WHITE CEMENT BOARD CLADDING

EXISTING FAILING WHITE COMPOSITE ALUMINIUM CLAD SINGLE GLAZED TIMBER WINDOWS

NOTE
This drawing is not to be scaled. Use figured dimensions only. All dimensions are to be checked on site and any discrepancies, errors or omissions are to be reported to the architect prior to commencement of works.

SCHEME DESIGN SUBJECT TO
STRUCTURAL ENGINEER / SERVICES ENGINEER,
& PLANNERS COMMENT

Rev	Notes	Date	By
-----	-------	------	----

PLANNING



Studios 33-34, 10 Hornsey St, London. N7 8EL
Tel 020 7336 8555 - e-mail - architect@bbpartnership.co.uk

Client

Project
Weeping Ash,
Oak Hill Park
London
NW3 7LP

Drawing
Existing Photos
Roof, Cladding, Window/ Door Materials

Date Oct 23	Scale NTS@A1	Drawn by LA
drg.no. GIC - 420	Revision -	

© 2022 BB PARTNERSHIP LIMITED - ALL RIGHTS RESERVED
DO NOT SCALE - CHECK ALL DIMENSIONS ON SITE