

New concrete slab floor installed in each arch with in-built services and utilities, and support for potential future mezzanine structures. Refer to: E108-500s drawings; Structural, Civil and MEP engineers information; and NBS E05.



1. Refer to the gazetteer for more information on the existing condition of each arch and external space.
2. As per the Preliminary UXO Risk Assessment, prior to or in lieu of a Detailed Assessment, it is recommended that appropriate UXO Risk Mitigation Measures are provided for intrusive works proposed.
3. All works within proximity to the historic structures are to implement relevant measures to protect historic fabric.
4. Works within proximity to TfL / NR structures and the approval processes / protections required, contractor to highlight in CPP and submit RAMS.

[illegible]