


Existing Front Isometric



No 22 Swains Lane
(sketch outline)

No 18 Swains Lane
(sketch outline)

FRONT DRIVEWAY
(not fully modelled)

incongruous flat roof to garage

rendered side wall (in poor condition)

Note: rainwater goods & drainage pipework not modelled for clarity

garage dominates front elevation

awkward junction between garage & bay partially obscures window

incongruous flat roof to rear bay

REAR GARDEN
(not fully modelled)

Planning