- RECORDING DEVICE - NEW (IN SAME LOCATION AS EXISTING)

IAP - INTRUDER ALARM CONTROL PANEL - NEW (IN SAME LOCATION AS EXISTING)

| - INTRUDER ALARM KEYPAD - NEW (IN SAME LOCATION AS EXISTING)


PB - INTRUDER ALARM PUSH PANIC BUTTON - ALL NEW (IN SAME LOCATION AS EXISTING)

— - INTRUDER ALARM SIREN - ALL NEW (IN SAME LOCATION AS EXISTING)


D - INTRUDER DETECTOR (DIRECTIONAL) - ALL NEW (IN SAME LOCATION AS EXISTING)

DOOR OPEN ALARM CONTACT - ALL NEW (IN SAME LOCATION AS EXISTING)

CCT REF. - INTRUDER ALARM CIRCUIT NO. DETAILS - SEE NOTE 2



- VISITOR ACCESSIBLE



notes

- 1. DOUBLE PUSH PANIC ALARM BUTTON CONNECTED TO THE INTRUDER ALARM. BUTTON MOUNTED ONTO UNDERSIDE OF TABLE.
  - THE EXISTING INTRUDER ALARM CIRCUIT NUMBER AND CABLING WILL BE RETAINED. SEE SQUARE MILE'S QUOTATION FOR FURTHER DETAILS.
- 3. INTRUDER SIRENS NOT ALL SHOWN. ALL TO BE REPLACED IN THE SAME LOCATION.
- 4. LOCATION OF AN INTRUDER ALARM EXPANDER AND RADIO RECEIVER FOR A MOBILE PANIC BUTTON ARE INSTALLED AT LOW—LEVEL.
- 5. WHERE PRACTICAL AND IT DOES NOT IMPAIR ITS OPERATION, ALL NEW & EXISTING DEVICES/EQUIPMENT ARE TO BE PAINTED (EVENLY & WITHOUT RUNS) SO AS TO MATCH THE SURROUNDING WALL/CEILING SURFACE TO WHICH IT IS
- 6. ALL REDUNDANT CABLING IS TO BE REMOVED AND ANY SURFACES MADE GOOD.

Notes	
Do not scale. All dimensions to be checked on Errors to be reported to supervising officer.	j

SYMBOLS	REDUCED	IN	SIZE	AND	NOTES	7	2r	8	SMC

- C INTRUDER ALARM EXPANDER, RADIO RECEIVER AND NOTE 4 ADDED.
- B AMENDED TO REV. B FOR ISSUING PURPOSES. S.M.
  A INCORPORATING ARCHITECTS COMMENTS. S.M.
- Pour



P.G.Wilkinson BSc MSc MRICS
City Surveyor

CITY SURVEYOR'S DEPARTMENT Corporate Property Group: Plans & Research Section

Project:
KEATS HOUSE
10 KEATS GROVE
LONDON NW3 2RF

Prawing:
FIRST FLOOR
EXISTING INT. ALARM &
CCTV SYSTEMS LAYOUTS

Des: S.M.C. App:

Date: Pro code
UPRN

Drawing No: COL/KH/68/101