

Application No:	Consultees Name:	Received:	Comment:	Response:
2024/3601/P	The Heath & Hampstead Society Society	01/10/2024 14:48:55	COMMNT	<p>OBJECTION From THE HEATH & HAMPSTEAD SOCIETY</p> <p>I have walked past this wall many times on the way to Keats House and admired it.</p> <p>As can be seen in photos nos. 3 & 4 much of the wall needs no work apart, perhaps, from careful colour-matched lime mortar (Not glaring cream-coloured mortar) throughout. As is usual in boundary walls of this age there has been historic movement but this only adds to the historic interest of the wall and is not in need of rebuilding.</p> <p>The elevations do not show which parts are to be repaired. It would be clearer if the existing elevations were drawn showing where work was to be done. The existing brick-on-edge coping must be retained. There is no detail cross-section of the wall at a larger scale</p> <p>The comments by Stephen Hayward are excellent and should be complied with.</p> <p>This wall can be made good at minimal cost. Please REFUSE this application and request a new application showing minimal work carried out by crafts men as detailed by Stephen Hayward.</p>

2024/3601/P	The Heath & Hampstead Society Society	01/10/2024 14:47:00	COMMNT	<p>OBJECTION From THE HEATH & HAMPSTEAD SOCIETY</p> <p>I have walked past this wall many times on the way to Keats House and admired it.</p> <p>As can be seen in photos nos. 3 & 4 much of the wall needs no work apart, perhaps, from careful colour-matched lime mortar (Not glaring cream-coloured mortar) throughout. As is usual in boundary walls of this age there has been historic movement but this only adds to the historic interest of the wall and is not in need of rebuilding.</p> <p>The elevations do not show which parts are to be repaired. It would be clearer if the existing elevations were drawn showing where work was to be done. The existing brick-on-edge coping must be retained. There is no detail cross-section of the wall at a larger scale</p> <p>The comments by Stephen Hayward are excellent and should be complied with.</p> <p>This wall can be made good at minimal cost. Please REFUSE this application and request a new application showing minimal work carried out by crafts men as detailed by Stephen Hayward.</p>
-------------	---------------------------------------	---------------------	--------	---
