

R	New 1/2HR FR veneer faced flush panel door stained finish
R1	New 1/2HR FR veneer faced flush panel door stained finish (Replacing original non-compliant flush panel door with paint finish)
R2	Replacement oak veneered 1/2 leaf, FR60 flush panel doors, vinyl wrapped, with vision panel to main level (Replacing later addition non-compliant oak veneered 1/2 leaf oak veneered flush panel doors & frames)
R3	Replacement oak veneered double leaf, FR60 flush panel doors, vinyl wrapped, with vision panel to both levels (Replacing later addition non-compliant oak veneered double leaf oak veneered flush panel doors & door frames)
RT1	Retained emergency stair (later addition) cherry veneer faced flush panel doors with vision panels to both levels clear finish.
RT1	Retained toilet (later addition) cherry veneer faced flush panel door, clear finish
RT2	Retained service riser (later addition) flush panel door, decorated finish
RT2a	Retained service riser (later addition) flush access panel decorated finish

Revision letter

