

This drawing is to be read in conjunction with associated drawings: SOAS-PB-DT-EX-001 Corridor Door Types - Level 1, 2 & 3 SOAS-PB-DT-EX-002 Corridor Door Types - Level 1, 2 & 3 SOAS-PB-L2P-EX-010 Level 2 Plan SOAS-PB-L4P-EX-010 Level 4 Plan

- R New 1/2HR FR veneer faced flush panel door stained finish to match surrounding retained joinery. (Replacing original non-compliant flush panel door with paint finish)
- R1 New 1/2HR FR veneer faced flush panel door with fixed overhead panel, stained finish to match surrounding retained joinery. (Replacing later addition non-compliant plastic laminate faced flush panel door with fixed plastic laminate faced overhead panel)
- R2 Replacement oak veneered 11/2 leaf, FR60 flush panel doors, vinyl wrapped, with vision panel to main leaf. (Replacing later addition non-compliant oak veneered 11/2 leaf oak veneered flush panel doors & frames)
- R3 Replacement oak veneered double leaf, FR60 flush panel doors, vinyl wrapped, with vision panel to both leaves. (Replacing later addition non-compliant oak veneered double leaf oak veneered flush panel doors & door frame)
- (RT) Retained emergency stair (later addition) cherry veneer faced flush panel doors with vision panels to both leaves, clear finish.
- (RT1) Retained toilet (later addition) cherry veneer faced flush panel door, clear finish
- (RT2) Retained service riser (later addition) flush panel door, decorated finish
- (RT2a) Retained service riser (later addition) flush access panel, decorated finish
- (RT3) Later addition (circa 2005 Library Refurbishment) FR60 flush panel doors with reveal cladding panels, ash veneered with clear finish



