

© BOWKER SADLER PARTNERSHIP LIMITED ■ THIS DRAWING IS THE SUBJECT OF COPYRIGHT WHICH VESTS IN BOWKER SADLER PARTNERSHIP LIMITED. IT IS AN INFRINGEMENT MEANS, INCLUDING ELECTRONIC, WITHOUT THE EXPRESS WRITTEN CONSENT OF BOWKER SADLER PARTNERSHIP LIMITED WHICH RESERVES ALL ITS RIGHTS BOWKER SADLER PARTNERSHIP LIMITED ASSERTS ITS RIGHTS TO BE IDENTIFIED AS THE AUTHOR OF THIS DESIGN ■ REPORT ERRORS & OMISSIONS TO ARCHITECT. ■ CHECK ALL DIMENSIONS ON SITE ■ DRAWING TO BE READ IN CONJUNCTION WITH THE HEALTH AND SAFETY PLAN AND ALL RELEVANT RISK ASSESSMENTS

Survey drawings are kindly provided by Malcom Hughes Land Surveys Ltd and are assumed to accurately describe the existing buildings, services and external spaces. Masonry Repairs Key

Rake out and repoint with lime mortar

New brickwork to match existing

Cut out individually badly weathered or


damaged bricks. Replace locally with new bricks to match existing approximately 30% of area shown

New window / door openings

Indent to approximately 120mm or to depth of window rebate detail



Indent / replace face of mullion if practicable, back to plane of window frame



Cut out and replace head or cill entirely

REV. DATE DRN.

The Hoo: Scheme 2 17 Lyndhurst Gardens, Hampstead, London, NW3 5NU Returning A Grand Victorian House To Private Domestic Accommodation

Mr and Mrs Yu
REPRESENTED BY
JAGA Developments (London)

Lodge Stone and Brick Repairs
Sections AA and BB

SCALE SHEET SIZE DRAWN CHECKED DATE
1:50 @ A0 ADS BH Apr 2020

BOWKER SADLER ARCHITECTURE A: Hatherlow House, Hatherlow, Romiley, Stockport SK6 3DY

T: 0161 406 7333 E: bsp@bowker-sadler.co.uk W: www.bowker-sadler.co.uk

19013 **PLANNING**