

Fig 11 Location of proposed projects (Hopkins Architects, dwg no HGC-HAL-XX-XX-DR-A-1000, rev P01, 22-10-2024)



Fig 12 Current Garden Staff & Equipment building and site of proposed East Side Building, looking west (MOLA photo 09, 22-06-2023)



Fig 13 Basement of current Garden Staff & Equipment building showing entrance to tunnel (MOLA photo 12, 22-06-2023)








Fig 14 Current Garden Staff & Equipment building Demolition Plans and Sections (Hopkins Architects, dwg HGC-HAL-CB-ZZ-DR-A-1000, rev P01, 22-10-2024)





Basement Level - Proposed

Fig 15 East Side Building Proposed Plans (Hopkins Architects, dwg HGC-HAL-CB-ZZ-DR-A-1010, rev P01, 22-10-2024)




Fig 16 East Side Building Proposed Sections (Hopkins Architects, dwg HGC-HAL-CB-ZZ-DR-A-1011 and 1013, rev P01, 22-10-2024)



Fig 17 Site of proposed West Side Building, looking west (MOLA photo 20, 22-06-2023)




Fig 18 Location of Perkins Monument to be relocated (MOLA photo 22, 22-06-2023)




Fig 19 West Compound Demolition Plan (Hopkins Architects, dwg HGC-HAL-VB-ZZ-DR-A-1000, rev P01, 22-10-2024)





Fig 20 West Side Building Ground Plan (Hopkins Architects, dwg HGC-HAL-VB-ZZ-DR-A-1010, rev P01, 22-10-2024)



Fig 21 West Side Building Sections (Hopkins Architects, dwg HGC-HAL-VB-ZZ-DR-A-1011, rev P01, 22-10-2024)



Fig 22 Dissenters' Chapel, looking east (MOLA photo 27, 22-06-2023)



3 Dissenters' Chapel - South Section Demolition .

Fig 23 Dissenters' Chapel - Sections - Demolition (Hopkins Architects, dwg HGC-HAL-DC-ZZ-DR-A-1000, rev P01, 22-10-2024)



Fig 24 Site of Courtyard Store, looking south-east (MOLA photo 16, 22-06-2023)



Fig 25 Site of Courtyard Store, looking south-east (MOLA photo 18, 22-06-2023)