				Printed on:	28/01/2025	09:10:02
Application No:	<b>Consultees Name:</b>	Received:	<b>Comment:</b>	Response:		
2025/0152/P	Mark Hodgkin	25/01/2025 14:45:09	INT	The drawing seems incomplete as in the previous application there was an ASHP in front of where the new door is. Where is the ASHP being moved to?		