



Scale in metres

Sky facing pediments and cill stonework indented and mortar

-Mortar repair to retained stonework of window surrounds.

-Cast iron rainwater goods de-rusted, repaired and redecorated.

-All timber windows repaired and redecorated, including replacing broken glazing and re-puttying

## Drawn Checked **CEROWSKI** ARCHITECTS

East Grinstead, West Sussex tel. 07495 980 757

/ 24/01/2025 L.B.C. Issue.

University College School

Facade Repairs, UCS, Hampstead, NW3 6XH

Existing North Block, East Elevation

UCSH.FR 041