



## Legend



Hack off and replace render to Clause M20/110



Provisional works. On inspection by structural engineer remove defective render and concrete to soffit and expose I beams. Treat metalwork as recommended by structural engineer and to recommended specification. Localised stonework repairs and to clause C41/240 and C41/245.



Brickwork stitch replacement to clause C41/365



Specialist two coat render repairs to internal face of lightwell retaining wall comprising undercoat two part hydraulic lime to 5 part sharp and top coat of 1 part hydraulic lime and 3 part sharp sand.



Cut out damaged slate DPC and replace with new natural slate bedded and pointed in 1:1:6 mortar to existing details



UCL

project

The Slade School of Fine Art Gower St London WC1E 6BT External Repairs

drawing title :

Basement Front Elevation repairs (Provisional)
As Proposed Sheet 2

## **FulkersBaileyRussell**

London | Basingstoke | Brighton | Bristol | Cardiff | Kings Hill | Manchester info@fulkers.co.uk // www.fulkers.co.uk // 020 3735 5792

scale:

1:100 @A1



4682-FBR-A1-XX-DR-A-221

S2 (For Information) rev no: P.01

