



EXISTING - SHOWING FLEMISH BOND AND CONCRETE LINTELS TO BE REINSTATED





1:10

