
## **APPENDIX 1 - 19<sup>TH</sup> CENTURY**

## Contents


- 1828 CT Mirror
- 1880 41 42 CT Repair to Curb Wall
- 1890 41 CT as Existing
- 1890 41 CT Basement Existing
- 1890 41 CT Ground Existing
- 1890 41 CT 1st Existing
- 1890 41 CT 2<sup>nd</sup> Existing
- 1890 41 CT 3rd Existing
- 1890 41 CT Section Existing
- 1890 41 CT as Proposed
- 1890 41 CT Basement Proposed
- 1890 41 CT Ground Proposed
- 1890 41 CT 1<sup>st</sup> Proposed
- 1890 41 CT 2<sup>nd</sup> Proposed
- 1890 41 CT 3rd Proposed
- 1890 41 CT Section Proposed
- 1890 41 CT Staircase Ground Proposed
- 1890 41 CT Staircase First Proposed
- 1890 41 CT Staircase Section Proposed
- 1897 41 CT Alterations to Skylight




1828 CT Mirror

10 y nov 80 Nº. 41 Chester Terrace. RECE The wall referred to by M. adamo is the curbor plinth wall of the Inclosure next the fortpath ( Park side ) - the damp which penetrales The wall has thrown off the paint and in parts the cement work, causing an unsightly appearance. My impression is that the only remedy which would be in any way effectual would be to cut down the cement work entirely to the face of the bruckwork and finish it anew in Portland bement as has been done by the brown Estate Paring Commit in the case of the similar wall to the Garden Enclosure of Chester Terrace. arthur later November 9 1880.


1880 41 42 CT Repair to Curb Wall




1890 41 CT as Existing




1890 41 CT Basement Existing




1890 41 CT Ground Existing




1890 41 CT 1st Existing




1890 41 CT 2nd Existing




1890 41 CT 3rd Existing




1890 41 CT Section Existing




1890 41 CT as Proposed




1890 41 CT Basement Proposed




1890 41 CT Ground Proposed




1890 41 CT First Proposed




1890 41 CT Second Proposed




1890 41 CT Third Proposed




1890 41 CT Section Proposed




1890 41 CT Staircase Ground Proposed



1890 41 CT Staircase First Proposed



1890 41 CT Staircase Section Proposed



1897 41 CT Alterations to Skylight