KEY

EXISTING BUILDING FABRIC

General

0

σ

•

•

.

4

.

4

.

φ.

· ·

The building is currently occupied and a large amount of items are being stored within the interior. This has prevented a full inspection being made as the stored items obscured some areas of the interior. It is possible to identify soem original features surviving and these have been indicated on the plans. In general the following outline specification is proposed. It is proposed to remove all existing surface mounted trunking and wiring etc. All existing wall mounted spur shelving to be removed.


Existing wall and celling surfaces

Many existing wall and ceiling surfaces are covered in woodchip wallpaper. In some areas, in particular ceilings, the paper is coming away from the substrate. Existing walls to have existing woodchip wallpaper removed. Wall surface to be made good as necessary and to receive plaster skim coat. Existing ceilings to have existing woodchip wallpaper removed. Ceiling surface to be made good as necessary and to receive plaster skim coat.

For full notes on proposals see application drawings

.Α

Hatched area indicates existing walls to be removed



Informal parks with the contractional dwink scale provides that transming, dwarman kindler of the dwing to dialong to be used in conjunction with structure why there provides the inpotential synchronic to	Syte wife (15 T DED 7724 8212 F 220 T34 8211		FOR APPROVAL Lorna Williams	44 Great Russell Street London WC1B 3PA	Second Floor Plan As Existing	scale checked by crawinc 1:50@A1 RW 178.103	
2011 syte archited's in tech check all dimensions to so projek (untimencement of file work if the crywing avoided the transmerine any way the architects groups to be informated and works for ensembled.	REV A 12.07.12 Revision to Planning and Listed Building fasce			orojec:	drawing title	cate drawn.ovy revision June 11 BM A	
	зB	STORE +31.43					