

0 1000 2000 5000 10 000mm

As existing plans and elevations based on measured survey carried out by The Downland Partnership Limited in May 2008.

GENERAL NOTES:

- Proposed works to external fabric of the building are largely
 to essential repairs to windows, render and subsequent
 redecoration. Limited roof repairs to existing slate roofs and
 replacement of 'failed' asphalt parapet gutters and flat roof
 areas are being carried out to maintain a weather tight
 structure. No alterations to existing setting and landscaping
- of the House are proposed.

 Proposed improvements to the external fabric are noted on the drawings and principally involve the replacement of the secondary entrance corridor and store rooms at the east end of the House to provide new service accommodation for the
- existing Kitchen.

 Where repairs allow, the opportunity to improve details or provide essential new facilities will be taken with provision of a 'fall arrest' system and a more discrete lightening
- protection installation.

 Renewal of building services should allow the improvement of the external appearance by the removal of modern external drainage pipework, roof mounted ventilation ductwork and plastic trunking associated with the Chiller
- The existing heating and electrical installations have partially failed, need to be replaced and will be carefully stripped out
- throughout the building.

 6 Light fittings will be retained wherever appropriate to the character of the building interiors and will be refurbished as
- character of the building interiors and will be refurbished as required

 7 Existing modern fan coil radiator casings are being removed
- and replaced with new sympathetically designed joinery and furniture pieces.

 8 Existing service and drainage routes will be used wherever
- possible with a presumption of minimum intervention with the historic fabric in all instances.

 These proposals do not envisage any significant structural alterations to the existing fabric, with all new partitions being formed as non-load-bearing plaster and lath studwork
- partitions within existing internal spaces.

 Generally existing floor finishes (carpet on plywood) are being replaced with new hardwood or stone floors to give a more appropriate finish and appearance subject to approval
- of sample.

 11 All bathrooms will be provided with stone tile surfaces with under-floor heating which will overlay existing flooring
- (strengthened) where necessary.
 12 A number of the modern 'dropped' suspended plasterboard ceilings are being replaced (consequence of removal of internal services ductwork and pipe runs) and will be replaced with new fibrous plaster ceilings and comices,
- reinstated closer to their original room height.

 13 Existing panelled door leafs, where no longer required are generally being re-used in alternative locations, while the
- modern glass door leaves will be discarded.

 14 Existing door linings will be retained, with a number of doors indicated for handing and re-hanging within existing
- Modern architraves and pre-fabricated skirtings will generally be replaced with a more appropriately detailed timber
- be replaced with a more appropriately detailed timber section. Refer to details No. 2191-01/03/20 + 21.
- Modern replacement ironmongery will generally be replaced with better quality, historically appropriate fittings throughout
- to approved samples.

 17 Existing 'dated' and poor quality internal decorations are being renewed with an emphasis on paint schemes that reinforce the more relevant and significant 'Pegeney'.
- reinforce the more relevant and significant 'Regency' character of the house.

Ke

Existing wall

_

Proposed walls and alterations

Walls, doors & items to be removed

Existing doors New doors

LBC3 07-09-10 location of existing satellite dishes amended

LBC2 31-08-10 location of proposed satellite dishes & security cameras

Date Reason For Issue

LISTED BUILDING CONSENT



MARTIN ASHLEY ARCHITECTS

The Stables, Friars Stile Road, Richmond, Surrey TW10 6NE
Fel: 020 8948 7788 - Fax: 020 8948 5520 www.martinashleyarchitects.co.uk

Client
HANLEY LIMITED


Project
BEECHWOOD HOUSE
RESTORATION AND IMPROVEMENTS


Title ROOF PLAN AS PROPOSED

Date Scale
Aug 2008 1/100@A1
Checked By VS PC
Drawing Number Revision


LBC3

Drawing Number **2191-01/01/04**





SOUTH WEST ELEVATION



As existing plans and elevations based on measured survey carried out by The Downland Partnership Limited in May 2008.

GENERAL NOTES:

- Proposed works to external fabric of the building are largely to essential repairs to windows, render and subsequent redecoration. Limited roof repairs to existing slate roofs and replacement of 'failed' asphalt parapet gutters and flat roof areas are being carried out to maintain a weather tight structure. No alterations to existing setting and landscaping
- of the House are proposed.

 2. Proposed improvements to the external fabric are noted on the drawings and principally involve the replacement of the secondary entrance corridor and store rooms at the east end of the House to provide new service accommodation for the existing Kitchen.
- existing Kitchen.

 Where repairs allow, the opportunity to improve details or provide essential new facilities will be taken with provision of a 'fall arrest' system and a more discrete lightening
- protection installation.

 4 Renewal of building services should allow the improvement of the external appearance by the removal of modern external drainage pipework, roof mounted ventilation ductwork and plastic trunking associated with the Chiller
- ductwork and plastic trunking associated with the Chiller pipework.
 The existing heating and electrical installations have partially failed, need to be replaced and will be carefully stripped out
- throughout the building.

 6 Light fittings will be retained wherever appropriate to the
- character of the building interiors and will be refurbished as required
 7 Existing modern fan coil radiator casings are being removed
- and replaced with new sympathetically designed joinery and furniture pieces.

 8 Existing service and drainage routes will be used wherever
- Existing service and drainage routes will be used wherever possible with a presumption of minimum intervention with the historic fabric in all instances.
- 9 These proposals do not envisage any significant structural alterations to the existing fabric, with all new partitions being formed as non-load-bearing plaster and lath studwork partitions within existing internal spaces.

Generally existing floor finishes (carpet on plywood) are

- being replaced with new hardwood or stone floors to give a more appropriate finish and appearance subject to approval of sample.

 11 All bathrooms will be provided with stone tile surfaces with
- under-floor heating which will overlay existing flooring (strengthened) where necessary.

 12 A number of the modern 'dropped' suspended plasterboard ceilings are being replaced (consequence of removal of
- internal services ductwork and pipe runs) and will be replaced with new fibrous plaster ceilings and cornices, reinstated closer to their original room height.

 13 Existing panelled door leafs, where no longer required are
- generally being re-used in alternative locations, while the modern glass door leaves will be discarded.

 14 Existing door linings will be retained, with a number of doors indicated for handing and re-banging within existing
- indicated for handing and re-hanging within existing openings.
 Modern architraves and pre-fabricated skirtings will generally
- be replaced with a more appropriately detailed timber section. Refer to details No. 2191-01/03/20 + 21.

 Modern replacement ironmongery will generally be replaced with better quality, historically appropriate fittings throughout
- to approved samples.

 17 Existing 'dated' and poor quality internal decorations are being renewed with an emphasis on paint schemes that reinforce the more relevant and significant 'Regency' character of the house.

Ko

Walls,doors & items to be removed

LBC3 07-09-10 location of existing satellite dishes amended

LBC2 31-08-10 location of proposed

Rev. Date Reason For Issue

LISTED BUILDING CONSENT



MARTIN ASHLEY ARCHITECTS

The Stables, Friars Stile Road, Richmond, Surrey TW10 6NE
Tel: 020 8948 7788 - Fax: 020 8948 5520 www.martinashleyarchitects.co.uk

Chk

Revision

LBC3

Client
HANLEY LIMITED

Project

BEECHWOOD HOUSE
RESTORATION AND IMPROVEMENTS

Title


EXTERNAL ELEVATIONS AS PROPOSED

Aug 2008 1/100@A1

Checked By
VS
PC

Drawing Number **2191-01/01/05**

2191-01/01/05© Martin Ashley Architects 2009



GENERAL NOTES:

- Do not scale from this drawing. Use figured dimensions only. Contractor to check dimensions on site prior to construction and
- notify CA of any discrepancy.

 This drawing is to be read in conjunction with all other relevant contract drawings, specifications & Schedules.
- If in doubt: Ask
 Martin Ashley Architects shall be notified in writing of any discrepancies.

LBC2 07/09/10 NOTE ADDED LBC1 31/08/10 FIRST ISSUE Rev. Date Reason For Issue

LISTED BUILDING CONSENT



MARTIN ASHLEY ARCHITECTS

The Stables, Friars Stile Road, Richmond, Surrey TW10 6NE Tel: 020 8948 7788 - Fax: 020 8948 5520 www.martinashleyarchitects.co.uk

HANLEY LIMITED BEECHWOOD HOUSE RESTORATION AND IMPROVEMENTS

Title EXISTING WINDOW WG15 &

PROPOSED WINDOWS WG32,WB17,WB18

Checked By

Date August 2010 | Scale 1:10@A3

Drawing Number 2191-01/05/04

Revision LBC2

© Martin Ashley Architects 2009

Drawn By VS