

Schedule of Remediation Works Undertaken

Date Reported	Name	Address (see attached aerial photo)	Date Notified TV Contractor	Date of Initial Reception Inspection	Proposed Works & Costs	Date Completed
Pre June 2008		29 Longford Street		Lost of satellite signal	Reconnected onto satellite dish, new aerial & lead 5/12/07. Box not working 19/12/07.	19 December 2007
Pre June 2008		Flat 11, 28 Longford Street		Lost of satellite signal	Satellite box not working. Not British Land responsibility.	17 January 2008
Pre June 2008		Flat 4, 29 Longford Street		Lost of satellite signal	Realigned sky dish 1/12/07. Cut cable, replaced cable.	08 December 2007
Pre June 2008		Flat 7, 28 Longford Street		Lost of satellite signal	Extended Sky cable and installed 2 way Inb 5/1/08. Realigned Sky dish.	09 January 2008
Pre June 2008		White House Hotel		19/3/08 Ghosting from Cranes	Test and install new cabling. Faulty repeater, White House to repair	06 April 2008
Pre June 2008		Windermere and Rothay	SCCI meeting 17/4/08	Lost of TV signal	22/5/08 Quote £3,504.50 New satellite controllers for each TV channels to return TV reception back to both buildings	30 June 2008
Pre June 2008		Esther Randell Court		Lost of TV signal	SCCI investigated 07/10/08. Satellite dish previously relocated by Ward Aerials. Need to check if faulty works or new development blocking signal.	Completed 19/5/08
Pre June 2008	Mrs Helena Reid	Walton House & One Housing		6/3/08 Ghosting on all channels	Replaced dish and cabling 27/3/08.	Works completed 17/10/08. Note issued to Anna Develet to advise Mrs Reid to contact Camden Housing Office directly as she refused access to retune the TV.
17 June 2008	Mr Amid	Flat 13, 26 Longford Street	23 June 2008	Report of lost satellite signal	SCCI investigated 07/10/08. Satellite dish previously relocated by Ward Aerials. Tenant have installed hotbird and wants Arabsat.	Tenant requested alternative satellite station which is not within British land remit
11 June 2008	Karen Stott	Flat 14, 26 Longford Street		Report of lost satellite signal	SCCI investigated 07/10/08. Satellite dish previously relocated by Ward Aerials. Ward Aerials unable to gain access to flat.	Complete 3/8/09
		Troutbeck	11 June 2008	Lost of TV signal	Requires SMATV	SCCI confirmed works completed 24/9/08
10 August 2008		St Mary Magalene Church, off Munster square	12 August 2008	Report of lost satellite signal	Church Father have relocated satellite dish, no further issue reported	Complete
08 September 2008		Flat 12, 26 Longford Street	08 September 2008	Cranes and hoarding blocking line of sight to satellite	SCCI investigated 07/10/08. Satellite dish previously relocated by Ward Aerials. Need to check if faulty works or new development blocking signal.	Complete 3/8/09
11 June 2008	Mr Wilkins	30 Chester Close South	11 June 2008	Report of lost TV signal	SCCI advised matter is left with Mr Wilkins and no further response received to date	SCCI advised property is too distant from development to be affecting TV signal
08 October 2008	Mrs Tibby	Rothay (Sharon Rodney reported matter)	08 October 2008	Report of lost TV signal	SCCI found faulty equipment and returned TV signal	Complete
08 October 2008	Angela Bennett	Flat 31, 9 Laxton Place, 07956586064	09 October 2008		SCCI to re-arrange visit	
08 October 2008		Flat 4 Rothay	08 October 2008	Report of lost satellite signal	Tree in way of satellite dish	Note forwarded to Anna Develet to advise Sharon Rodney to deal with directly.
16 October 2008	Jean Herman	Troutbeck	16 October 2008	Lost of TV signal	Requires SMATV	SCCI confirmed works completed 24/9/08
23 October 2008		Silverdale	23 October 2008	Report of lost TV signal	SCCI are advising that through their Camden maintenance, this building is started to be affected by the development. I have requested if the patch manager to raise formal complaint and then instruct SCCI to remedy TV reception before more complaints are received. Instructed SCCI 9/12/08	Complete
09 April 2009	Susan Bradshaw	Flat 21, Southern Collesium Terrace, Albany Street, NW1 4EB	12 April 2009	Report of TV signal being affected	SCCI reported that the TV reception maybe affected by the tower cranes. A post signal test is proposed after removal of the last tower crane. Also SCCI identified that the building satellite cabling to the flats are old and are losing signal strength. This is not a British Land responsibility	SCCI instructed to carry out TV signal test
07 April 2009	Mr Katie	Flat 8, Walton House	16 April 2009	Report of lost TV signal	Signal returned as part of the One Housing works	Complete 3/8/09
	Corrado Gurini	Longford Street		Report of lost TV signal	SCCI to run catinary from One Housing	Complete 3/8/09