Az 21/12 M. PANEZ

<u>Case officer:</u> Donna Hipkins	
Application Number: PE9800773	LONDON BOROUGH OF CAMDEN TOWN ACTS AND TO AMINING ACTS
<u>Address:</u> Oldfield Estate, Jaqueli Fitzroy Rd, NW1	ne, Carple, and Marion House,
Proposal: Retention of roof safety EN BERALF OF THE COUNCIL	
Drawing Numbers: 6008 3i,ii,iii.	

**RECOMMENDATION SUMMARY:** 1. FPC (Without standard 5 year condition)

# OFFICER REPORT:

- 1. <u>SITE</u>
- 1.1 Purpose built complex of flats situated at the corner of Fitzroy/Regents Park Rd, within Primrose Hill C.A.
- 2. <u>PROPOSAL</u>
- 2.1 The roof safety guard rail is to provide protection to roof perimeters for regular maintenance repairs. It has already been erected.
- 3. <u>RELEVANT</u> <u>HISTORY</u> None
- 4. <u>RELEVANT POLICIES</u>
- 4.1 Borough Plan UD18
- 4.2 Draft UDP EN33
- 5. <u>CONSULTATIONS</u>
- 5.1 CAAC Accept the principle of the guard rail, but consider that the temporary appearance of the railings to be inappropriate and should be consistent with the design of the building.

Royal Parks (CRPA) - No comment received.

Adjoining Occupiers Site Notice Only

## 6. <u>ASSESSMENT</u>

- 6.1 Main considerations impact on character and appearance of building within a CA.
- 6.2 The purpose of the guard rails is for both yearly maintenance for asphalt repairs and more regular maintenance by the caretaker to unblock gutters, etc.

The appearance of the rails is rather utilitarian and somewhat like scaffolding. However, because of the number of large trees surrounding the buildings, it is very difficult to clearly see the rails either from Regents Park Rd, Fitzroy Rd or from the Park opposite.

Although these purpose built blocks have little architectural merit, the rails do not enhance the buildings. If they are to be a permanent feature, a better design and material would be desirable, as commented by the CAAC.

The Agents have informed us that the cost of erecting temporary rails on a yearly basis was prohibitive and still did not meet the safety requirements, because of the need for ad hoc maintenance. We are told that the cost of the rails and their installation was £15,000. Although it is felt that the rails are not ideal, as they are already erected, it would be unreasonable to insist on their removal and replacement. A compromise would be to give a temporary permission to allow the Housing Trust to budget for replacement rails and a review of the situation at the end of that time.

## 7. **<u>RECOMMENDATION</u>** (P9800773)

7.1 That planning permission be granted subject to the following conditions:-

## **Conditions**

1. The limited period for the retention of the railings shall be until 31 January 2002 by which date the structure shall be removed. (CC02)

#### <u>Reasons for Conditions</u>

1. The type of railings are not such as the Council is prepared to approve, other than for a limited period, in view of their appearance in a Conservation Area.

\*(Admin: remove standard condition)\*

	Property 1 the second property	
Gueen's	The second secon	
	The and the adverter of the comments of the co	
N 39-330	Charles Charle	
STREET		
ROTHWELL SALES	5 22,7	
To Character Star	3	
The the second	I have the the	
The second secon	Reptingent Place	
The second secon		
1 1 1 2		
F I F T		
38.7m		
Activity of the second se		
Ponds Basel		
	n House 13 14	
36.4m	Salasta Astronomical Strategy	
	N/30 // Fr I / Has Lon 1	
	Clarter 1 1 1	
	2 2 - Tran	
	the terms	
	34.8m Sg Sg	
	the second se	
	Dir Contraction of the second s	
Reproduced from the QS map with the permission of the Controller. of H.M.S.O. Licende No. CA086339.		
London Borough of Camden Chiliph Repto		
Environment Department	Marlen Ksao	
Town Hall Extension	turnoy Road	
Argyle Street Entrance	- )	
London WC1H 8EQ		