

## UNISON HQ, EUSTON RD NORTH London, WC1

Summary Report on the Required Emergency Remedial Works
To the Listed Buildings at the former Elizabeth Garrett Anderson Hospital

February 2007

Ref: L051036

Revision 0

Job: UNISON HQ, EUSTON RD NORTH, LONDON WC1 Ref: L051036 - Revision 0 Date: February 2006



**CONTENTS** 

SUMMARY

**APPENDICES** 

Revision		Ву	Checked	Date
0	Issued for Planning Approval/ Tender	PL	PL	21/02/07

Job: UNISON HQ, EUSTON RD NORTH, LONDON WC1

Ref: L051036 - Revision 0 Date: February 2006



### 1.0 Summary

- 1.1 UNISON has purchased the former Elizabeth Garrett Anderson Hospital with the intention of re-developing the site as their main London offices.
- This report outlines the minimum structural works which are required to be undertaken in order to stabilise the listed building. This report should be read in conjunction with the AKSWard report entitled, 'Report on Investigations and Required Remedial Works to the Listed Buildings at the former Elizabeth Garrett Anderson Hospital', which contains more details of the investigations undertaken and provides a more detailed background.
- To summarise, the detailed report named above, explains that the portion of the listed building fronting Euston Road has been subsiding for a period of up to 10 years. Monitoring of the listed building has proved that the listed building is continuing to subside. This subsidence has caused severe damage to the listed building to the point where certain parts of the building fabric must be dismantled and re-built.
- The listed buildings are founded within the underlying London Clay, the clay is highly plastic. The water demand of the mature trees on the corner of Churchway and Euston Road has caused extensive soil dessication of the underlying London Clay. This dessication has caused the clay to shrink, leading to movement of the foundations. All the structural movement and cracking can be associated to the movement of the foundations which can be attributed to the adjacent trees.
- The movement due to subsidence is so severe and has been occurring for such a long period, that parts of the listed building cannot now be saved. The cracking is so severe in certain areas that, to prevent the imminent catastrophic collapse of parts of the listed building, areas have been propped both internally and externally.
- The listed building is continuing to subside and further structural damage will occur progressively unless action is taken. The building fronting the Euston Road must be underpinned such that the foundations are extended to below the depth of the dessicated clay.
- 1.7 As the clay is dessicated to a depth of 4m, the building is to be underpinned through the use of piles. The drawings contained within this report are the minimum works which are required to be undertaken to ensure that the building stops moving. If these works are not undertaken, further movement could cause further more serious damage and parts of the listed building fabric could be lost.
- To facilitate the underpinning, the site should be cleared and these works are described upon drawing number L051036/LB-01. The bay shall be carefully dismantled in accordance with the Conservation Architect's requirements, and the internal ground floor slab shall be removed (refer to drawing numbers L051036/02 and L051036/03). Following these works the building can be underpinned in accordance with the drawings.

Job: UNISON HQ, EUSTON RD NORTH, LONDON WC1

Ref: L051036 - Revision 0 Date: February 2006



- 1.9 In conjunction with the underpinning, it is further recommended that the main brickwork arches are also repaired to ground, first and second floors. These arches are currently supported on temporary props.
- 1.10 Following undertaking these works, it is considered that the building will have been stabilised and the structural movement will have ceased. It is considered that the building can only be fully renovated following completion of these 'emergency works'.
- 1.11 It should be noted that only the works presented within this document, and the accompanying Conservation Architect's details, are proposed to be undertaken as part of the emergency stability works.

Job: UNISON HQ, EUSTON RD NORTH, LONDON WC1 Ref: L051036 - Revision 0

Date: February 2006



Appendix A

Drawings Submitted For Planning Approval/ Tender


# Document Register & Issue

Project

UNISON HQ. Euston Road North

roject No: L051

Sheet No: 1	Day		01	01	21													
	Month		02	02	02		$\neg$											
	Year		07	07	07						-							
ocument Title	Doc. No.	Size		· · · · ·	· · · · ·			• • • • •								ssu	e/Re	vis
······································								-										
Site Clearance Drawing	LB-01		Α	Α	Α					"								
Demoston Street 1	LB-02		Α	Α	В													
Denit Bir - Breef 2	LB-03		Α	Α	В											$\dashv$		
			<u> </u>						_						_	<b></b> -}	-	
Underplanting Layout	LB-10		A	Α	Α									_		$\dashv$		
			Α	Α	Α									<u>-                                    </u>				$\dashv$
Trial Philippine - One Floor Levels	13-12		A	Α	Α											$\dashv$	$\dashv$	
Pling Option 2	LB-13		Α	Α	Α			.										
1st & 2nd Floor Plan (Wall Restraints)	LB-20	<u> </u>	P1		<u> </u>		•						<u></u>			$\dashv$		
18t Ct Zild 1 loof 1 ldif (17cm 1 tooddinia)	1		-							· · · -								
Typical Crack Repair Details	L9-25		Α	Α	Α													
Floor Repair Detail	LB-26		<u> </u>			<u> </u>												
Estamal Ossala Lagation Desiring 1	LB-30		P1								<u> </u>							
External Crack Location Drawing 1	LB-30	-	P1					├	. !	·	-		_					
External Crack Location Drawing 2	LB-31	<del>                                     </del>	P1	-	├	<u> </u>					(*************************************					,		
External Crack Location Drawing 3	LB-32 LB-33	-	P1	<del> </del>	<del> </del>	<u> </u>	72	agilik kudharra			~		ORIGINAL PROPERTY.					
Internal Crack Location Drawing 1		<del> </del>	P1			-			<u></u>			_		<del>                                     </del>				
Internal Crack Location Drawing 2	LB-34	$\vdash$	P1	<u> </u>	<del> </del>	$\vdash$	<del>                                     </del>	<u> </u>				<del> </del>		<u> </u>	<u> </u>			
Internal Crack Location Drawing 3 Internal Crack Location Drawing 4	LB-35 LB-36	<del>                                     </del>	<u>     </u>   P1	$\vdash$	<del>                                     </del>	<del> </del>					╁┈┈							
Internal Clack Location Diawing 4	LD-30	<del>                                     </del>		+		╁		_			├─			1	-			
Arch Repub Grat, Internal View Shoot 1	LB-60		A	A	Α			<del>                                     </del>			<del>                                     </del>							
Arch Repair Gnd. Chast 2	LB-61		~	1	1			<u> </u>					<u> </u>		<u> </u>			<u> </u>
	1 - 45	<u> </u>	↓_	_	ļ·	_	<u> </u>		<del> </del>			<del> </del>	ļ		├			
Arch Repair 1st Floor Internal View	LB-40	-	A	A	A		├	_	-		1	<u> </u>	<del>]</del>	<del> </del>	ļ			
Arch Repet 2nd Floor Internal View	LB-70	<del> </del>	A	A	A	+	<del>                                     </del>	ļ <u>-</u>	<del>                                     </del>	├			┼┈	-	-			
Arch Pages 2nd Floor Internal View	1.8-71	1	$\frac{1}{A}$	<del></del> -	<del>-[</del>	<del>  "</del> -	<del> </del>	┼-			$\top$		<del>                                     </del>	<del> </del>	<del> </del>		<del>                                     </del>	
			1								<u> </u>							
		<u></u>				<u>                                     </u>			<u> </u>	<u> </u>			<u> </u>	<u>.l</u>				
Status I: Information P: Preliminary B: B	uilding Contro	ol A: A	/ppro	vai T	T: 1	Fende	<b>≆</b>	C: C	onstr	uctic	<u> </u>	R: I	₹ <b>eco</b>	<u>1</u>	Ar. A	vchiv	/ <del>e</del>	<u> </u>
					1		<u> </u>	!	<u> </u>	J	<u> </u>	1	<u> </u>	Ш.	<u> </u>	<del></del>	l <u> </u>	
	· <del>- </del> -		—-	l	<u> </u>									<del></del>	<del></del>	$\overline{}$		[
Type of Issue			17	 	1./	<del>-</del>	<del> </del>	1	Ι	ī	1		I	Į.	1	_L	╄—	┼
Type of Issue Рарег			<u> </u>	<b>√</b>	1	<u> </u>	-				-			<u>                                      </u>	+	T	1	ı
Type of Issue Рарег Disk			<u> </u>	<b>→</b>	<b>✓</b>										-		<del> </del>	<del> </del>
Type of Issue Paper Disk E mail			<b>✓</b>	<b>✓</b>	<b>√</b>										Nt	ımbı	or of	Co
Type of Issue Paper Disk E mail Distribution			1	1	1	<u> </u>								1	Nt	ımbı	or of	Co
Type of Issue Paper Disk E mail Distribution John Cole (Unison)			1 1	1 1	1 1										Ne	ımbı	DF O	Co
Type of Issue Paper Disk E mail Distribution John Cole (Unison) Tim Chambers (Drivers Jonas)			1 1 1	1 1 1	1 1 1										Ni	ımbı	Dr of	Co
Type of Issue Paper Disk E mail Distribution John Cole (Unison) Tim Chambers (Drivers Jonas) Faye Shelley (Gerald Eve)			1 1 1	1 1 1	1 1 1										Nt	ımbı	Dr of	Co
Paper Disk E mail Distribution John Cole (Unison) Tim Chambers (Drivers Jonas) Faye Shelley (Gerald Eve) Michael Poots (Squire & Partners)			1 1 1 1	1 1 1 1	1 1 1 1 1										Nt	imb		Co
Paper Disk E mail Distribution John Cole (Unison) Tim Chambers (Drivers Jonas) Faye Shelley (Gerald Eve) Michael Poots (Squire & Partners) Jon Whyte (Davis Langdon LLP)			1 1 1 1 1	1 1 1 1 1	1 1 1 1										Ne	imb	or of	Co
Distribution  John Cole (Unison)  Tim Chambers (Drivers Jonas)  Faye Shelley (Gerald Eve)  Michael Poots (Squire & Partners)  Jon Whyte (Davis Langdon LLP)  Mark Fisher (Foreman Roberts)			1 1 1 1 1	1 1 1 1 1	1 1 1 1 1										Ne	imb	Dr of	Co
Paper Disk E mail Distribution John Cole (Unison) Tim Chambers (Drivers Jonas) Faye Shelley (Gerald Eve) Michael Poots (Squire & Partners) Jon Whyte (Davis Langdon LLP)			1 1 1 1 1 1	1 1 1 1 1	1 1 1 1 1										Ne	imb		



This drawing in the copyright of AKSWard, it may not be copied allered or reproduced in any way without their written authority.
This drawing must not be scaled. Use figured dimensions only. If in doubt ASKI

- This drawing is to be read in conjunction with all relevant AKSWard drawings and specification(s) profited £651036
- All setting out to be in accordance with the Architects
  drawings. Any discrepancies between the Engineers and
  the Architects drawings to be referred to the Architect
  before proceeding. Dimensions must not be scaled.

Denotes assumed line of Existing Drainage (To be temporarily diverted to allow piled underpinning)

**TENDER** 

# AKSWard<sup>®</sup>

## CONSTRUCTION CONSULTANTS

EC1A BJU


Tel: 020 7236 0161 Fex: 020 7230 3239

e-mail: london@akaward.com web; www.aksward.com


UNISON HEAD QUARTERS

## SITE CLEARANCE DRAWING

AS 1:100
Date 25.01.0
Date
Drg No. Rev.
LB-01 A
_



- This drawing is to be read in conjunction with all relevant AKSHard drawings and specification(s) prefixed LESTOSS



TENDER

# **AKSWard**

## CONSTRUCTION CONSULTANTS

ECKA SJU

Tel: 020 7236 0161 Fex: 020 7236 3239 e-mail: london@akswerd.com

☐ Windhester ☐ Poole ☐ Sherborne

C Carlord

Project UNISON HEAD QUARTERS

DEMOLITION - SHEET 1

Reviewed Scheme P.L. L061036 LB-02

FIRST FLOOR

**GROUND FLOOR** 

SECOND FLOOR

THIRD FLOOR

Ground, First and Second Floors archee to be repaired prior to undertaking demolition

\* All areas of demolition to be re-installed in accordance with the Conservation Architects drawings

Demoition to be undertaken as part of emergency stability works.

\* All areas of demolition to be re-installed in accordance with the Conservation Architects drawings

COPYRIGHT


This drawing is the copyright of AKSWard, it may not be copied altered or reproduced in any way without their written authority.


This drawing must not be scaled. Use figured channelone only. If in doubt ASK?

### NOTES

- This drawing is to be read in conjunction with all relevant


  ACSMissed drawings and specificalization profession LOS1038
- All setting cut to be in accordance with the Architects drawings. Any discrepancies behaves the Engineers and the Architects drawings to be referred to the Architect before according. Discrepance many act he accord





رات مادی برهمی معنی در ایمانیان ک	MP	PL.	21.2.07
A Consed updates	98	PL.	25.01.07
Rev. Amendment	Dm	Chkd	Dela
Drg Status TENDE	R		-
AKSW	/a	r	d <sup>®</sup>
CONSTRUCTION CO	N\$U	LTAN	tTS
One West Smithfield	(	Lond	on .
London EC1A 9JU	(	) Oxfor	d
ECIABO	(	□ Wind	heeter
Tel: 020 7238 0161	1	D Poole	
Fast: 020 7236 8230	1	3 Sheri	oome
e-meil: fondon@ekswerd.com web: www.ekswerd.com			
Client/ Architect UNISON			
Project UNESON HEAD Q	ŲAK	TER	)

Scales A1	A3	
Reviewed Scheme P±	Date	25,01.07
Reviewed Final	Dete	
Project No.	Drg No.	Rev.
L051036	LB-03	



## PILE SCHEDULE

PILE No.	DEAD LOAD	LIVE LOAD	SWL (M)	PILE CUT OFF LEVEL	PILE DRIVING LEVEL
M M	72	19	160	To be confirmed	To be confirmed
	173	19	200		
- 62	101	9	125	<del></del>	· · · · · · · · · · · · · · · · · · ·
		19	100		
04	72	<u> </u>		. <u> </u>	1
<b>Q</b> 6	72	10		<u> </u>	
Då	72.	16	100		
97	72	16	100	<u> </u>	
ÇE .	163	#	200		
09	91	6	125		
10	91		100		·
11	91	8	125		
	138	11	175		
12		<del>                                     </del>	426		
13	130	5/	275		
	198				<u></u>
15	91	<u> </u>	180		
16	et e		125		
17	74	22	135		<u> </u>
19	74	22	100		
**	74	22	175		·
25	74	22	160		
	104		189		
51		39	160		<u> </u>
	104	20	160	<del></del>	
23	104		190		
24	104	**		<del></del>	
25	-30.5	25.5	-159	_	
*	104	30	190		
27	-30.5	25.5	-180		
2	104	30	160		<u></u>
<u> </u>	426.5	37	500		
36	134	38	175		
	500.5	57	575	_ <del></del>	
\$1	<u> </u>		275		<del></del>
<b></b>	100	<b>8</b>			
23	MA	NA.	NA NA		
34	176	12	425	·	
25	375	12	425		
*	376	12	45		
77	376	12	436		
*	275	2	435	· ·	
	-73	4	-400		
	-73	<u> </u>	-100		
	<u></u>		-100	<del>-  </del>	
	-73		-100		
4	-73				
49	-73	4	-100	<u> </u>	
44	166	0	220		
46	278.5	98.5	150		
46	398	**	300		
47	<b>253</b>	75	380		
· ·	21	1	176		
		45	176		
<del></del>	-87		-75	· · · · · · · · · · · · · · · · · · ·	
	<u> </u>		-300	<del></del>	
	-167		435		
	312	M		<u> </u>	<u></u>
6	-40	-20	-100		
54	27	22	76		<u> </u>
#		草	76		
	- 77	32	76		
	57	12	75		
	17	2	Ti Ti		
<del></del>	37		75		
			75		· <del>-   </del>
<b>—</b>	17		76		
61		<b>82</b>			
42	**	발	75		
				. 1	6
ø	#7	<b>1</b>	75	<u> </u>	

## A NEGATIVE LOAD INDICATES TENSION PILE

### COPYRIGHT


This denoting is the copyright of AKSWard, it may not be copied altered or reproduced in any way without their written authority.

This drawing must not be scaled. Use figured dimensions only. If in doubt ASK?

### NOTES

- This drawing is to be read in conjunction with all relevant

  AKSMard drawings and specification(s) probable
- All setting out to be in accordance with the Architects drawings. Any discrepancies between the Engineers and the Architects drawings to be returned to the Architect before proceeding. Discussions must not be scaled.




Typical Piling Details.


A Commissi updates	DB	PL_	20.01.07
Rev. Amendment	Dm	Chied	Deta
Drg Status TENDER			
AKSV	_ ^/a	r	<b>⊿</b> ②
,	<b>—</b>		
CONSTRUCTION	CONSU	LIA	415
One West Smithfield	!	■ Lond	on
		□ Oxfo	-4
London			-
London EC1A BJU		□ Wind	
EC1A BJU		□ Wind	hepter
		_	hepter b

	<del></del>
Title	PILE SCHEDULE & DETAILS

Project UNISON HEADQUARTERS

Scales	A1	1:25	A3	1:59
Reviewed	Scheme	PL	Date	29.01.07
Reviewe	i Final		Date -	
Project N	a.		Drg No.	Rev.
L0510	36		LB-11	A





ALTERNATIVE TO UNDERPHNING SYSTEM PALI RADICE TYPE SYSTEM

> Fully designed & detailed system to be developed by specialist subcontractor

## NOTE:

System may not be suitable to elevation fronting Eusto Road due to proximity of London Undergroud Tunnels (Circle Line). Specialist piling contractor to be consulted

This drawing is the copyright of AKSWard, it may not be copied effected or seproduced in any way without their written authority.

This drawing must not be scaled, Use figured dimensions only. If in doubt ASKC

Dry State TENDER **AKSWard** 

## CONSTRUCTION CONSULTANTS

EC1A 9JU

Tel: 020 7236 0161 Fas: 020 7236 3239 e-mail: london@elaward.com


☐ Sherborne

□ Oxdord

Project UNISON HEADQUARTERS

Title PILING OPTION 2

Scales	A1	MA.	AS	
Reviewe	Scheme	PL.	Date	25,81,07
Raviewe	) Final		Date	
Project N	<u>a.</u>	'	Drg No.	Rev.
L0510	36		LB-43	A



## KEY:

and replaced using lime morter

INDICATIVE CRACK REPAIR DETAIL Not to Scale

Denotes Ericks adjacent to cracks to be out out and cleaned and reinstand

1. Architectural feature bricks to be reinstated / replaced as necessary 2. Crack to be repaired to Full depth of Walf

This drawing is the copyright of AKSWard, it may not be copied altered or reproduced in any way without their written authority.

This drawing must not be scaled. Use figured dissensions only. If in doubt ASKO

- This drawing is to be read in conjunction with all relevant AKSYVard drawings and specification(s) professio L061038
- All setting out to be in accordance with the Architects drawings. Any discrepancies between the Engineers and the Architects drawings to be referred to the Architect before proceeding. Dimensions must not be scaled.

TENDER  $AKSWard^{0}$ 

# CONSTRUCTION CONSULTANTS

London EC1A 9JU

C) Conford ☐ Poole


□ Sherborne

Tel: 020 7236 0161 Fax: 020 7230 3239

Project UNISON HEAD QUARTERS

TYPICAL CRACK REPAIR DETAIL

Scales	<u>.</u> <b>A</b> 1	1:50	A3	1:100
Reviewed		P.L.	Date	25.01.07
Reviewed	Final	<u> </u>	Dete	
Project N	<u> </u>		Drg No.	Rev.
1 8248	44		1 R-25	•



Floor to be propped.

Arch to be taken down and

rebuilt to match existing. Arch to be replaced with steel beams. (Refer to drg. L051036 - LB51)

COPYRIGHT

This drawing is the copyright of AKSWard, it may not be copied altered or reproduced in any way without their written authority.

This drawing must not be scaled. Use figured dimensions only. If in doubt ASK!

This drawing is to be read in conjunction with all relevant AKSWard drawings and specification(s) prefixed L051036

All setting out to be in accordance with the Architects drawings. Any discrepancies between the Engineers and the Architects drawings to be referred to the Architect before proceeding. Dimensions must not be scaled.

A General updates

Rev. Amendment

TENDER

# **AKSWard**<sup>®</sup>

CONSTRUCTION CONSULTANTS

One West Smithfield London EC1A 9JU

Tel: 020 7236 0161 Fax: 020 7236 3239 e-mail; london@aksward.com ☐ Winchester ☐ Poole ☐ Sherborne

web: www.aksward.com


Client / UNISON

Project UNISON HEAD QUARTERS

ARCH REPAIR GROUND LEVEL INTERNAL VIEW SHEET 1 of 2


SHEET	1 01 2		
Scales A1		A3	
Reviewed Scheme	P.L.	Date	25.01.07
Reviewed Final		Date	
Project No.		Drg No.	Rev.
L051036		LB-50	A

3



INTERNAL ELEVATION ON GROUND FLOOR ARCH AT BAY

A3 Scale 1: 20



SECTION A-A
A3 Scale 1:10

### COPYRIGHT

This drawing is the copyright of AKSWard, it may not be copied altered or reproduced in any way without their written authority.

This drawing must not be scaled. Use figured dimensions only. If in doubt ASK!

### NOTES

- This drawing is to be read in conjunction with all relevant AKSWard drawings and specification(s) prefixed L051036
- All setting out to be in accordance with the Architects drawings. Any discrepancies between the Engineers and the Architects drawings to be referred to the Architect before proceeding. Dimensions must not be scaled.

Rev. Amendment Dm Chkd Date

Drg Status Preliminary

# **AKSWard**<sup>®</sup>

■ London

□ Oxford

☐ Poole

☐ Winchester

☐ Sherborne

## CONSTRUCTION CONSULTANTS

One West Smithfield London

London EC1A 9JU

Tel: 020 7236 0161 Fax: 020 7236 3239


e-mail: london@aksward.com web: www.aksward.com

Client / UNISON

Project UNISON HEAD QUARTERS

ARCH REPAIR
GROUND LEVEL
SHEET 2 of 2

OHLL	1 & 01 4	•	
Scales A1		А3	1:20
Reviewed Scheme	P.L.	Date	25.01.07
Reviewed Final		Date	
Project No.		Drg No.	Rev.
L051036		LB-51	



COPYRIGHT

This drawing is the copyright of AKSWard, it may not be copied altered or reproduced in any way without their written authority.

This drawing must not be scaled. Use figured dimensions only. If in doubt ASK!

### NOTES

- This drawing is to be read in conjunction with all relevant AKSWard drawings and specification(s) prefixed L051036
- All setting out to be in accordance with the Architects drawings. Any discrepancies between the Engineers and the Architects drawings to be referred to the Architect before proceeding. Dimensions must not be scaled.

A General updates DB PL 25.01.07

Rev. Amendment

AKSWard<sup>®</sup>

TENDER

## CONSTRUCTION CONSULTANTS

One West Smithfield London EC1A 9JU

☐ Oxford
☐ Winchester
☐ Poole

☐ Sherborne

Tel: 020 7236 0161 Fax: 020 7236 3239 e-mail: london@aksward.com web: www.aksward.com

Client / Architect UNISO

Project UNISON HEAD QUARTERS

FIRST LEVEL
INTERNAL VIEW

Scales A1 A3


Reviewed Scheme P.L. Date 25.01.07

Reviewed Final Date


Project No. Drg No. Rev.

L051036 LB-60 A

INTERNAL ELEVATION



repaired locally. All cracks indicated to be repaired by cutting out broken bricks and cutting back adjacent Brickwork. Brickwork to be replaced in Lime Mortar





COPYRIGHT

This drawing is the copyright of AKSWard, it may not be copied altered or reproduced in any way without their written authority.

This drawing must not be scaled. Use figured dimensions only. If in doubt ASK!

This drawing is to be read in conjunction with all relevant AKSWard drawings and specification(s) prefixed L051036

All setting out to be in accordance with the Architects drawings. Any discrepancies between the Engineers and the Architects drawings to be referred to the Architect before proceeding. Dimensions must not be scaled.

☐ Oxford

☐ Poole

□ Winchester

☐ Sherborne

Rev. Amendment

**TENDER** 

# **AKSWard**

CONSTRUCTION CONSULTANTS

London EC1A 9JU

Tel: 020 7236 0161 Fax: 020 7236 3239

e-mail: london@aksward.com web: www.aksward.com


Client / UNISON

Project UNISON HEAD QUARTERS

**ARCH REPAIR** SECOND LEVEL
INTERNAL VIEW

11412	MINTER A	17-44	
Scales A1		A3	
Reviewed Schem	e P.L.	Date	25.01.07
Reviewed Final		Date	
Project No.		Drg No.	Rev.
L051036		LB-70	A

INTERNAL ELEVATION



## **EXTERNAL ELEVATION**

### COPYRIGHT

This drawing is the copyright of AKSWard, it may not be copied altered or reproduced in any way without their written authority.

This drawing must not be scaled. Use figured dimensions only. If in doubt ASK!

### NOTES

- This drawing is to be read in conjunction with all relevant AKSWard drawings and specification(s) prefixed L051036
- All setting out to be in accordance with the Architects drawings. Any discrepancies between the Engineers and the Architects drawings to be referred to the Architect before proceeding. Dimensions must not be scaled.

Α	General updates	DB	PL	25.01.07
Dov	Amandment	Dm	Chkd	Data

Rev. Amendment

TENDER

# AKSWard

### CONSTRUCTION CONSULTANTS

One West Smithfield London EC1A 9JU

☐ Oxford
☐ Winchester
☐ Poole

☐ Sherborne

Tel: 020 7236 0161
Fax: 020 7236 3239
e-mail: london@aksward.com
web: www.aksward.com

Client / UNISON

Project UNISON HEAD QUARTERS

ARCH REPAIRS
SECOND LEVEL
EXTERNAL VIEW

Scales A1	А3	
Reviewed Scheme	P.L. Date 25.01.07	
Reviewed Final	Date	
Project No.	Drg No. Rev.	
L051036	LB-71 A	