

SE BAND 01/5/2013.


DE-ABANDONMENT OF SMALL POWER DATA
TRAINING TO TAKE ACCOUNT OF CONSERVATION
OFFICER COMMENTS.

PROPOSED REDUCED TRAINING
EXISTING TRAINING NOW REMOVED.

ORIGINAL TRAINING
OMITTED.


SOCKETS, NEW FEO VIA CONDUITS,
BURN IN FLOOR VOID.

TRAINING OMITTED.



REFRIGERANT LEAK DETECTION

VIEW 1 N.T.S



REFRIGERANT LEAK DETECTION
ROOM 2 PLAN
SCALE 1:50

INFORMATION			
contract no.	scale	1 : 50 @ A3	
client ref.	Argent	date	FEB '13
drawn by	GP	checked by	
drawing no.	4142	SERV	SKE02
			11

project	Stanley South Building - Building E1
title	STANLEY BUILDING ROOM 2 TYPICAL LAYOUT



BAM Design Ltd
BAM Design Limited
Crestwood Business Park
Crestwood Way, 12th Floor
Hertfordshire, AL1 2ED
T: 01727 884200
E: design@bam.co.uk
W: www.bam.co.uk

Architectural
Structural Engineering
Environmental Services
Interior Design
Planning & Policy Studies
3D Visualisation

rev	by	date	chkd	amendments
11	GP	20-02-13	MP	ARCHITECTS COMMENTS & REFRIGERANT LEAK DETECTION INCORPORATED
10	GP	12-02-13	MP	ISSUED FOR INFORMATION