



Missing timber

Existing timber requiring refurbishment

Timber recommended to be replaced

The shade to EW/G.21 exists but is in bad condition and will require substantial repair and replacement.



|   |                        |  |  |
|---|------------------------|--|--|
| Luard Conservation<br>67 Salford Avenue<br>London NW10 4EP<br>+44 (0)20 8061 7544<br>+44 (0)7963 741 117<br>info@luard-conservation.com | The Elms, Fitzroy Park |  |  |
|   | EW/G.21                |  |  |
|   | NOT TO SCALE           |  |  |