

Links Construction Limited 158 Herkomer House+High Street+Bushey+Herts+WD23 3HF

Client:

L Kelin

Date: 07/05/14

Address:

Flat 1, 20 Harley Road, NW3 3BN

Ref: est140501ob

ESTIMATE: External Common Part Works.

Area	Work Required	Cost £
Front		
External	Remove damaged patio area.	
	2. Dig out 300mm of soil and loose hard core from under.	
	3. Lay new type 1 MOT hard core.	
	4. Compact type 1 to solid surface.	
	5. Supply and fit new slabs on to 75mm of sand and cement bedding mortar.	
	6. Remove damaged party or boundary walls.	
	7. Dig out wall foundation to reasonable depth. At least 350mm depth.	
· .	8. Rebuild wall to existing level.	
	9. Render wall to existing finish.	
	10. Remove damaged left hand stair case wall area.	
	11. Dig out wall foundation to reasonable depth. At least	
	350mm depth.	
	12. Rebuild wall to existing level.	
	13. Render wall to existing finish.	
	14. Tidy all cable and pipe works for the works to progress	
	15. Clean area after finishing work.	

TOTAL PRICE

Parking to be provided for.

PLEASE NOTE:

That all works are for budget purpose only as the we can fully understand the extent of the works until a building surveyor is employed, who will produce a full specifation.