

SECTION AND WALL NOTES AT 34, BROOKFIELD ROAD LONDON NW5-SK2A REV A GROUT FILLED GAP NOTED TO ENG PRICKS RPH Engineering
Consulting Civil and Structural
Engineers
116 Turkey Street
Enfield EN1 4PS