
6.0 Appendix


Historic Plans:


- 1957 Ground Floor Plan
- 1957 6th Floor and Roof Plans

Guidelines for management drawings:


- Ground Floor Plan AnalysisRoof Plan Analysis
- Section AA Analysis
- Section BB Analysis
- Section CC Analysis
- Ground Floor Plan Guidelines
- 6th Floor Plan Guidelines
- Roof Plan Guidelines







		Key
		/ 1957 Original building fabric
		1982 Core areas refurbished
		1987 Extensive refurbishment
		1996 New glass roof over Congress Hall, office toilet
		areas refurbished 1998 Construction of Invision conference facility and
		refurbishment of first floor offices 1999 Meeting rooms
		Canteen
		2000 General Secretary's flat refurbished, conversion of 3rd and 4th floor to open plan
		2001 Congress Hall and Foyer areas refurbished
		2002 Conference facilities and main reception refurbiched, fifth floor
		refurbished, fifth floor meeting rooms and toilets refurbished.
		2003 General Secretary's Suite, Marble Hall, kitchen and toilet areas refurbished
	Ba	
	inbri	
	dge Street	
	Stre	Pev. Date By Description
	et	Drawing Status
		Hugh Brought on Architects 4 Addison Bridge Pace, London W14 8XP Tet 020-7602 8840 Fax: 020-7602 5254
		TUC - CONGRESS HOUSE GUIDELINES FOR
		MANAGEMENT Appendices
		Drawing Title
ŧ,		Ground Floor
		Existing
		Scales 1:200 Originator HBA
		Checked Approved Date April 2002 Job No. Drawing No. Pev. 69218 G -
11 1		



1957 Original building fabric 1982 Core areas refurbished 1987 Extensive refurbishment 1996 New glass roof over Congress Hall, office toilet areas refurbished 1998 Construction of Invision conference facility and refurbishment of first floor offices 1999 Meeting rooms constructed to replace Canteen 2000 General Secretary's flat refurbished, conversion of 3rd and 4th floor to open plan 2001 Congress Hall and Foyer areas refurbished 2002 Conference facilities and main reception refurbished, fifth floor meeting rooms and toilets refurbished. 2003 General Secretary's suite refurbished, kitchen and toilet areas refurbished, comfort cooling system replaced. Rev. Date By Description Drawing Status Hugh Brought on Architects 4 Addison Bridge Place, London W14 8XP Tel: 020-7602 8840 Fax: 020-7602 5254 lob Titl TUC - CONGRESS HOUSE GUIDELINES FOR MANAGEMENT Appendices Drawing Title Roof Plan Existing Ove Arup & Partners® ARU 13 Fitzroy Street London W1P6BQ Tel:02076361531Fax:0207580392 Л Scales 1:200 @ A3 Originator HBA


Checked


Appro

Drawing

Date April 2002

Key







Courtyard North Elevation / Section BB

A3

Areas of Special Architectural and Historic


Main Reception and Marble Hall Entrance, Sculpture and disabled ramp Memorial Wall with Epstein Sculpture Marble Hall viewing gallery





Courtyard South Elevation / Section CC

Key	
	1957 Original building fabric
	1982 Core areas, Council Chamber refurbished
	1987 Extensive refurbishment
	1996 New glass roof over Congress Hall, office toilet areas refurbished
	1998 Construction of Invision conference facility and refurbishment of first floor
	offices 1999 Meeting rooms constructed to replace Canteen
	2000 General Secretary's flat refurbished, conversion of 3rd and 4th floor to open
	plan 2001 Congress Hall and Foyer areas refurbished
	2002 Conference facilities and main reception refurbished, fifth floor meeting rooms and toilets refurbished.
	2003 General Secretary's Suite, Marble Hall, kitchen and toilet areas refurbished
Bev Dat	
Rev. Dat	e By Description
Drawing S	
Drawing S	tatus
Drawing S	
Job Title	tatus
Job Title TUC GUII	tatus
Job Title GUII MAN	tatus
Job Title GUII MAN	tatus
Job Title GUII Drawing T COUI	tatus
Job Title GUII Drawing T COUI	tatus
Job Title TUC GUII MAN Appeing T Court Sect	tatus
Job Title TUC GUII MAN Appe Exist	Addies Broughton Architects 14.000-7602 5840 Fixe, London Wirk 929 14.020-7602 5840 Fixe, COV-7602 5254 3- CONGRESS HOUSE DELINES FOR JAGEMENT endices Ite tyard South Elevation ion CC ting



Areas of Special Architectural and Historic Interest

16 Caretakers Flat



Кеу
3.1 Areas of low architectural and historic significance Internal alterations in these areas will not need listed building consent if the design guidelines prescribed in section 4.1 are followed.
3.2 Areas of moderate special architectural and historic interest Internal alterations in these areas will affect the special architectural and historic interest of the building and will therefore need listed building consent and, where the guidelines are followed, are likely to receive it.
3.3 Areas of high special architectural and historic interest Alterations will affect the special architectural interest of the building. In order to gain Listed Building Consent, it will be necessary to provide full design details for the proposals and fully justify the practical need for any alterations to these areas
3.4 Areas of very high special architectural and historic interest Any alteration in these areas will not be permitted as they would have a significant impact on the special architectural and historic interest of the building.
Rev. Date By Description Drawing Status
Hugh Brought on Archit ects 4 Addison Bridge Place, London W14 8XP Tel: 020-7602 8840 Fax: 020-7602 5254
TUC - CONGRESS HOUSE GUIDELINES FOR MANAGEMENT
Section 3
Sixth Floor
Analysis of Special Architectural & Historic Interest
ARUP Ove Arup & Partners® 13 Fizzoy Street London WIP F800 Tel:02076361531Fac207500324 Scales 1:200 Originator HBA
Checked Approved Date April 2002
Job No. Drawing No. Pev. 69218 06 -

