

DO NOT SCALE FROM THIS DRAWING DRAWING TO BE READ IN CONJUNCTION WITH ALL OTHER ARCHITECT'S AND ENGINEER'S CONTRACT DRAWING & SPECIFICATIONS. ANY DISCREPANCIES MUST BE BROUGHT TO THE ATTENTION OF THE ARCHITECT IMMEDIATELY. THE CONTRACTOR MUST VERIFY ALL DIMENSIONS BY SITE

MEASUREMENT BEFORE ORDERING MATERIALS OR MANUFACTURING SUBSTITUTE MATERIALS & PRODUCTS TO THOSE NAMED WILL BE ACCEPTABLE IF PROVEN TO BE OF EQUAL OR HIGHER PERFORMANCE AND NOT IN CONFLICT WITH OTHER ELEMENTS.

All drawings are based on a scaled PDF not a survey. All dimensions to be checked on site and confirmed with Conservation Architect.

SCALE 1:100 (A1) METRES



Black powder coated stainless steel grilles



## General Note:

Due to limited roof access, inspection undertaken from ground level and tower parapet. Carry out a closer roof inspection, by scaffolding, to ascertain any repairs required to slates, battens, underlay, gutters and flashing's. Replace slates and lead flashing to all areas of roof as RGA condition survey and specification and LSA recommendations.

- 19/12/2014 For DAC

FOR DAC

Christ Church

Hampstead East Elevation

**Proposed Repairs** 

1:100 (1:200@A3) Dec14

## **RICHARD GRIFFITHS ARCHITECTS**

5 Maidstone Mews, 72-76 Borough High Street, London SE1 1GN T +44(0)20 7357 8788 | F +44(0)20 7403 7887 **E** admin@rgarchitects.com | www.rgarchitects.com