

Mr D Savic  
DS design solutions  
561 Finchley Road  
LONDON  
NW3 7BJ

29 January 2015

Our Ref: **15020-let1-AS**

Dear Mr Savic

**Re: Site supervision relating to tree issues at 48 Elsworthy Road, London, NW3**

I am writing to confirm my supervision visit to the above site on 28 January 2015. This visit was in response to planning conditions imposed by the London Borough of Camden, relating to the development of the property.

During that visit, I met with Mr Porat (Project Manager) and Mr Bhudia (Site Manager) and we inspected the tree protection measures installed on site. We referred to the Barrell Tree Consultancy tree protection plan 11189-BT1, and Keith Macgregor tree protection plan TPP 13/718 001. From my inspection, I can confirm that all the tree protective measures are in place as set out on the plans.

During my visit, I took photographs as a permanent record of the site conditions and include a selection below.



**Photo 1:** Tree protection barriers at the front of the property



**Photo 2:** Tree protection barriers at the rear of the property

Prior to work commencing on site, the fencing will be cross braced with a scaffolding framework and the Local Planning Authority Tree Officer will be invited to inspect the tree protection.

Please call me if you need to discuss any of these points.

Yours sincerely

Andy Sherlock **TechCert(ArborA) DipArb(RFS) FArborA MICFor CEnv**

**Copy:** Mr Porat (HRP Partnership)