



Keyplan

NOTE: These plans are based on preliminary survey drawings and are subject to change until final revisions are issued.

	GENERAL SCOPE OF WORKS	R:\10
1	Lifts Existing lifts to be removed and chimneys opened up to create new lobby area. New steel framed lift shafts with lightweight external cladding installed with 3no.new 13 person guest lifts and associated lift pits.	0089\PlanCt
	Lift 1 to serve B1 to 8th Floor. Llfts 2 & 3 to serve GF to 7th. Lift Engineer to confirm depth of lift pit; Structural Engineer to confirm B1 supporting steelwork. Substrate/ground conditions to be investigated to determine requirements for foundations. All lift works and foundations to be in accordance with structural engineer's requirements.	nest\T-(To
2	Feature Staircase Existing dog-leg stair removed and new 'grand' staircase incorporated to ground floor, including increase of ground floor slab opening. All works to be in accordance with structural engineer's requirements and developed in accordance with AD'K' and interior designer's design intent drawings. Requirement for fire shutter to be confirmed by Fire Engineer.	R:\10089\PlanChest\T-(TownPlanning)\10089-T-01-0220-ZB1.dgn
3	Lobby Hard refurbishment to include new fire rated doors to escape corridors - Fire Engineer to advise. Ground floor slab opening for existing spiral staircase infilled.)\10089-
4	Meeting Rooms & Corridor Existing meeting rooms retained in existing configuration - soft refurbishment of finishes only, existing doors retained, reused & refurbished where possible, new furniture. Extent of bespoke FF&E and/or contractor casegoods e.g. credenzas to be confirmed.	T-01-0220-
5	Lift Pit for 'Sesame' Lift Gear Hard refurbishment to existing escape corridor & plant rooms (new internal & external walls, door, external ramp) Lower Ground Floor slab level retained. Services route for electrical requirements to be confirmed by Services Engineer. All lift works and support to be in accordance with structural engineer's requirements.	ZB1.dgn
6	Unisex WCs to Meeting Rooms Hard refurbishment with new underground drainage and services. Works to include new partitions, ceilings, sanitaryware, doors/ironmongery and all finishes.	
7	Leisure Facilities Hard refurbishment of existing back of house areas to create new Leisure areas with reception, gymnasium & changing rooms within existing double height space. New mezzanine floor with stairs to Lower Ground Escape route retained as indicated by hatched area.	
8	Entrance to Meeting Room Relocated New opening created for double doors.	19/12
9	Support to New Ground Floor External Seating Location, size and base details for new steelwork to be confirmed by Structural Engineer.	9/12/2014
10	New Steelwork to Support Ground Floor Configuration Size, base details and demolition of existing internal walls for installation of new steelwork to be confirmed by Structural Engineer.	
11	2no. New Food Hoists Refer to Lift Engineer & Catering Consultant's specifications. New partition & door to conceal hoists.	
12	F&B WCs Hard refurbishment with new underground drainage and services. Works to include new partitions, ceilings, sanitaryware, doors/ironmongery and all finishes. Vanity unit to be contractor casegoods item co-ordinated with interior designer's design intent drawings and services engineer's requirements.	
13	Kitchen Existing kitchen & wash-up reconfigured and refurbished. Refer to Catering Consultant's equipment layout and specifications - to be co-ordinated with Architect's BOH Finishes Schedule. To include all ancillary areas such as cellars, cold room, freezer room, dry store, wash up area etc. and to link with satellite kitchens on ground floor. Existing dumb waiters and service lift to be retained & refurbished.	
14	Staff Canteen Hot and cold servery and drinks provision to be retained as existing.	
15	Plant Rooms Refer to Service's Engineers equipment layout and specifications.	
16	Refuse, Servicing and Goods In Card baler, glass crusher & compactor to be incorporated.	
17	Laundry Room & Housekeeping Office Retained as existing - redecoration only.	
18	Administration Offices 9 no. Finance staff located within open plan office and 4 no. HR staff within cellular offices. Fire Engineer to advise loss of external door.	
19	Staff Changing Rooms Reconfigured and refurbished in existing location - allow for new cubicles, sanitaryware, vanity, lockers etc. Staff and locker numbers to be confirmed. Existing raised floor within Female Changing Room area investigated and level access created if possible.	
20	Existing External Stairs (Meeting Room) Existing stairs removed within combined meeting room - Fire Engineer to advise. Replace with window to match adjacent existing.	
21	Cellar Existing Cellar location and python runs to be determined and retained as existing if feasibly possible	
22	Business Centre Requirements of Business Centre to be confirmed.	
	GENERAL NOTES	
	 Extent of original elements to be retained and restored is to be advised by Heritage Consultant and planning process. Following strip-out, the refurbishment works will require general making good of all substrates (soffits, ceilings, floors & walls) to enable extent of new finishes required. Refer to elevations for further detail on external works and works to facade e.g. windows. 	

Refer to elevations for further detail on external works and works to facade e.g. windows.
 Extent of bespoke FF&E and/or contractor casegoods elements to be confirmed.

