

Application No:	Consultees Name:	Consultees Addr:	Received:	Comment:	Response:
2015/3960/P	Mr Alex Khosla	Flat 2 51 St Augustine's Road London NW1 9RL	26/08/2015 21:10:54	COMMNT	<p>The current position of the boiler flue directly below the sash window of the flat above has been harming their amenity because the fumes emitted are entering the upstairs flat.</p> <p>Additionally, the flue currently projects over the public footpath emitting fumes in the faces of pedestrians and the vertical clearance from the footpath to the underside of the flue is insufficient to allow the safe passage of pedestrians beneath it.</p> <p>I support the proposed re-positioning of the boiler flue as it resolves the issues with its current position. The enforcement process to reposition the flue has taken many months therefore this matter needs to be resolved urgently. The proposed flue position is set back from the front of the building, within the boundary walls and would blend in with the existing drainage pipes. This is a satisfactory solution.</p>
