Tenanted office (h38.91) s36.85 Office (fc38.81) 36.19 Office 36.18 (fc38.93) Office (fc38.94) 36.20 Office (fc38.92) 36.18 (h38.62) s36.84 Kitchen (fc38.85) 36.20 (fc38.70) 36.17 Lobby (fc38.70) 36.19 36.18 (fc38.70) Office (fc38.85) 36.18 Office (fc38.91) 36.17 (h38.37) (d38.26) Cup'd Stairs To Fourth Floor s36.84 (h38.90) ≨ Lobby (fc38.97) 36.22 Office (tc38.91) 36.17 (38.44) Meter in cup'd s36.83 (h38.90) (fc38.62) 36.18 Office (fc38.97) 36.18 (h38.52) (d38.18) Office (fc38.92) 36.17 s36.83 (h38.90)

(fc38.63) 36.19

(h38.22) Toilet

(h38.19) Toilet

(h38.52)

Lobby (fc38.62) 36.19

s36.83 (h38.90)

Tenanted office

Design, materials and construction detailing to be carried out by trase ordination.

All rade packages to be carried out under warrantees by contractor.

- REFER TO ARCHITECT'S SPECIFICATION AND ASSOCIATED ADDENDA.

The main contractor/Management Contractor is responsible for co-ordination of the scope and sequence of all Sub-Contractors' work.

Office (fc38.93) 36.19

Store Room (fc38.62) 36.19

Lisale from this drawing:

1. all dimensions on site.

1. all dimensions on site.

wells to be read in conjunction with topographical survey

red to site inspection.

1. and three documentation (as applicable) and & all

menus prepared by other consultants.

produce with this of party agreements

PLA

PLANNING

Existing building layout is based on survey conducted by SDP Surveys of St Albans in October 2012

Notes

01 Third Floor Plan

E1-103 SCALE 1:50

**ColladoCollins**Architects

Devonshire Metro Ltd. Museum House, 25 Museum St EXISTING Third Floor Plan

E1-103

P1