STADEFL STADEFL STATE	
50 10 FFL SIGNTH FLOOR SIGNTH FLOOR SIGNTH FLOOR SIGNTH FLOOR SIGNTH FLOOR SIGNA FFL SIGNA F	
R2 370 FFL	
49 810 FFL	
SKTH FLOOR MRD FLOOR 40 A0 FFL SOURTH FLOOR 40 ZAO FFL INTO FLOOR 17 440 FFL SECOND FLOOR 30 10 FFL IRST FLOOR 30 10 FFL SECOND FLOOR 30 10 FFL SECOND FLOOR 30 10 FFL SECOND FLOOR 30 10 FFL SECOND FLOOR	
*3 840 FFL **********************************	
40.750 FFL	
37:440 FFL SECOND FLOOR 34.090 FFL SECOND FLOOR 30:110 FFL MEZZANINE FLOOR 20:110 FFL SECOND FLOOR 20:200 FFL SECOND FLOOR 24:300 FFL SECOND FLOOR 25:300 FLOOR	
HIRST FLOOR 30.110 FFL MEZZANINE FLOOR +27.240 FFL BROUND FLOOR -27.240 FFL PAVEMENT LEVEL 23.060 FFL	
MEZZANINE FLOOR +27.240 FFL SROUND FLOOR -24.300 FFL PAVEMENT LEVEL -23.060 FFL	Brick Brick AB
+27.240 FFL SROUND FLOOR -24.300 FFL PAVEMENT LEVEL -23.060 FFL	Vent Terracotto Brick Terracotto
24.300 FFL ▼	Terracotta
-23.060 FFL	18 RUSSELL ROOMS
BASEMENT FLOOR -20.000 FFL	Terracotto
North	Image: Constraint of the second s

Keyplan

Notes:

1. Do not scale

2. Contractor to Check all dimensions and report omissions and errors to the Architect



Elevation 4 - Bernard Street

Note: For street elevations showing perimeter fencing and Ground Floor External Strip-out details, refer to Epr drawing 10089-T-01-9000-Z00.

Refer to separate Elementa elevations for Services proposals.

Refer to separate LDI for external lighting proposals.

Green clouds represent changes since original application in March

2 REVISED & ISSUED FOR PLANNING

01 ISSUED FOR PLANNING

No Revision

01.10.15 MG

03.03.15 MG TN Date Initial Chkd ---- Focus Areas for External Restoration Works - refer to separate Harrison Goldman report for details

			· _ · _ · _ · _ · _ · _ · _ · _ · _ · _
Terracotta			
		Russell Hotel Bloomsbury Proposed North Eleva	30 Millbank London SW1P 4DU +44 (0) 20 7932 7600 www.epr.co.uk
		PLANNING Project No Type Blg	1: 100 @ A1 03.03.15