


Layouts presented for reference only, refer to Consented Application 2012/6865/L for details


 All external facades to be restored and cleaned generally

 Unsympathetic modern materials and security measures to be removed

 All exterior brickwork to be carefully cleaned, repaired and repointed where necessary in matching materials

External works. General notes:





 New solid access stair with bike wheel ramp to cycle store

Λ.....

 Existing boundary wall to be underpinned and repaired

> New timber framed two storey construction sleeved into existing fabric

 New double glazed infill to existing opening

 New external painted metal stair to connect to first floor

 Existing front screen wall to workshop be repaired and repointed

 New external painted metal fencing to access path

 Existing kitchen block to be rebuilt with facing brick